

ASS. REC. BY:

REF:

146/ 21003040/Kb

C

Henneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 18713

Yr Regn:

06, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vior

c.c.

1496

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

89394

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR2B23F3601131359

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 112

185/60R15

R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

D

mm

R/Bal.

3

mm

L/Bal.

D

mm

L/Bal.

3

mm

D.O.A.

4/3/21

D.O.I.

9/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/3 11:24 @ 2400 Confirmed

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLE3209C
Accident Date : 04-Mar-2021

No. : 06356

Date : 05-Mar-2021

Our Ref : 021038 (AIG) / CHAN

PAGE : 1

CHIN HUI CAR RENTAL
7 SIN MING INDUSTRIAL EST SECTOR C
#01-76
Singapore 575642

Not Authorized
Repair by paint
4 days
CL Rep 824001

ESTIMATED COST OF REPAIR FOR TOYOTA VIOS SMC1871B

- 1 pc Rear bumper fascia
- 1 pc Rear bumper reinforcement
- 2 pcs Rear bumper side retainer
- 1 pc Rear end panel
- 1 pc End panel top garnish
- 1 pc Boot lid
- 1 pc Boot lid logo
- 1 pc Boot lid "VIOS" emblem
- 1 pc Boot lid "E" emblem

	Bu	554.10	—
	Bu	346.80	—
@ S\$139.70	MSD	279.40	—
	R	582.80	—
	MSD	232.10	—
	Bu	754.30	—
	na	52.20	—
	na	53.60	—
	na	49.60	—
		2,904.90	—
Less 25% :		726.22	—

1 pc Rear bumper parking sensor(set

2,178.68 200sn
300.00 sn

To apply undersealing

80.00 *300*

To remove spare tyre ,rear seat,
trim board and carpet

120.00 *500*

To putty and spray replaced parts

800.00 *600*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 *500*

Total : S\$ 4,178.68

Singapore Dollars Four Thousand One Hundred and
Seventy Eight and Cents Sixty Eight Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: