

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21003041/EVD3Q2

Date: 23/03/2021

REFERENCE

Insured/Claimant:	CAROL GOH SU LIN	Policy No:	1900247889	
Date of Loss:	03/03/2021	Nature of Claim:	OD	Claim No: 6886851819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ3489J			
Make & Model:	KIA SORENTO, 2.2 (A)	Engine No:	D4HBGH274353	
Reg. Date:	07/11/2016 (Man. Year: 2016)	Chassis No:	KNAPH81BMG5222255	
Colour:	White	Odometer:	86303 km	
Engine Capacity:	2199 cc			
Market Value/New Car Price:	S\$85,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 ZR19	Rear Tyre Size:	235/55 ZR19
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,167.00	3,990.40	9,176.60	69.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,150.00	1,750.00	44.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,067.00	6,140.40	10,926.60	64.02
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	16,467.00	5,540.40	10,926.60	66.35
+ GST 7.00/7.00% (S\$)	1,152.69	387.83	764.86	66.35
Nett Amount (S\$)	17,619.69	5,928.23	11,691.46	66.35

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 08/03/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COOLANT (4L)	Not Necessary	26.00 FS	*- FS
2	1		*PANEL ASSY-HOOD	Dented	1,654.00 F	*1,654.00 FL
3	1		*LATCH ASSY-HOOD	Not Necessary	104.00 F	*- FL
4	1		*STRIP ASSY FR-HOOD	Torn	27.00 F	*27.00 FL
5	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 F	*13.00 FL
6	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	760.00 F	*- FL
7	1		*BEAM COMPLETE-FR BUMPER	Bent	551.00 F	*551.00 FL
8	1		*GRILLE ASSY-RADIATOR	Cut	738.00 F	*738.00 FL
9	1		*COVER-FR BUMPER UPR	Crushed	645.00 F	*645.00 FL
10	1		*MOUNTING ASSY-LICENCE PLATE	Cut	37.00 F	*37.00 FL
11	1		*COVER-FR BUMPER,LWR	Broken	645.00 F	*645.00 FL
12	1		*SKID PLATE-FR BUMPER	Cut	220.00 F	*220.00 FL
13	1		*LIP-FRONT BUMPER	Not Necessary	65.00 F	*- FL
14	1		*GRILLE-FRONT BUMPER	Broken	178.00 F	*178.00 FL
15	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	134.00 F	*134.00 FL
16	1		*STIFFENER ASSY-FR BUMPER LWR	Not Necessary	117.00 F	*- FL
17	1		*BRACKET-FR BUMPER SIDE,LH	Broken	17.00 F	*17.00 FL
18	1		*BRACKET-FR BUMPER SIDE,RH	Broken	17.00 F	*17.00 FL
19	1		*GRILLE-FRONT BUMPER FOG LAMP,L	Not Necessary	93.00 F	*- FL
20	1		*GRILLE-FRONT BUMPER FOG LAMP,R	Not Necessary	93.00 F	*- FL
21	1		*LAMP ASSY-FRONT FOG,LH	Not Necessary	297.00 F	*- FL
22	1		*LAMP ASSY-FRONT FOG,RH	Not Necessary	297.00 F	*- FL
23	4		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	748.00 F	*- FL
24	2		*ULTRASONIC SENSOR-S.P.A.S SIDE	Not Necessary	692.00 F	*- FL
25	1		*WIRING HARNESS-FR BUMPER	Not Necessary	296.00 F	*- FL
26	1		*LAMP ASSY-HEAD,LH	Not Necessary	2,210.00 F	*- FL
27	1		*LAMP ASSY-HEAD,RH	Not Necessary	2,210.00 F	*- FL
28	1		*GARNISH ASSY-FNDR SIDE,LH	Not Necessary	88.00 F	*- FL
29	1		*GARNISH ASSY-FNDR SIDE,RH	Not Necessary	88.00 F	*- FL
30	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
31	1		*HINGE ASSY-HOOD,RH	Bent	87.00 F	*87.00 FL

(Supplementary)

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,167.00	4,983.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	992.60
Total Parts (\$)	13,167.00	3,990.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,BONNET & FRT SUPPORT PNL.REPAIR/RE-ALIGN LHF FENDER & RHF FENDER	New	2,000.00	800.00
2	RESPRAY FRT BUMPER,BONNET,LHF FENDER & RHF FENDER	New	1,400.00	1,050.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
6	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	80.00	60.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
8	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
9	TOP UP AC GAS	New	80.00	0.00
Gross Labour Cost (\$\$)			3,900.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >