LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG21003042/EQD3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 **Date:** 30/03/2021

REFERENCE

Insured/Claimant: TAN SUI LIN Policy No: 1900049902

Date of Loss: 08/03/2021 Nature of Claim: OD Claim No: 3101068594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ9395U

 Make & Model:
 CITROEN C3, 1.6 (A)
 Engine No:
 10XK132277926

 Reg. Date:
 26/03/2019 (Man. Year: 2018)
 Chassis No:
 VF72RHNZWJ4371182

Colour: Red Odometer: 13129 km

Engine Capacity: 1199 cc
Market Value/New Car Price: \$\$70,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Hankook 4 mm Rear Left Side: Hankook 4 mm
Front Right Side: Hankook 4 mm
Rear Right Side: Hankook 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 3,911.60 | 2,480.80 | 1,430.80 | 36.58 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,555.00 | 3,435.00 | 1,120.00 | 24.59 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 8,466.60 | 5,915.80 | 2,550.80 | 30.13 |
| + GST 7.00/7.00% (S\$) | 592.66 | 414.11 | 178.55 | 30.13 |
| Nett Amount (S\$) | 9,059.26 | 6,329.91 | 2,729.35 | 30.13 |

INSPECTION

Date of Assignment: 08/03/2021

Cycle & Carriage France Pte Ltd (Pandan

Date Inspected: 08/03/2021 Inspected At: Gardens) (HQ)

209 PANDAN GARDENS

Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|---------------------------------------------------|--------------------------------------------------|------------------------|------------|------------|
| 1 | 1 | | *SUNDRY | Necessary | 20.00 FS | *20.00 FS |
| 2 | 1 | | *REAR BUMPER | Dented | 942.00 F | *942.00 FL |
| 3 | 1 | | *OVERRIDER LH | Dented | 615.00 F | *615.00 FL |
| 4 | 1 | | *BUMPER MOULDING | Cut | 482.00 F | *482.00 FL |
| 5 | 1 | | *BUMPER BRACKET | Not Necessary | 249.00 F | *- FL |
| 6 | 1 | | *BUMPER BRACKET | Not Necessary | 155.00 F | *- FL |
| 7 | 1 | | *BRACKET SET LATERAUX D/G | Broken | 432.00 F | *432.00 FL |
| 8 | 1 | | *BUMPER BRACKET | Not Necessary | 418.00 F | *- FL |
| 9 | 1 | | *BADGE ASS | Necessary | 73.00 F | *73.00 FL |
| 10 | 1 | | *BADGE | Necessary | 58.00 F | *58.00 FL |
| 11 | 1 | | *BADGE | Necessary | 58.00 F | *58.00 FL |
| 12 | 1 | | *WING PROTECTOR LH | Cut | 188.00 F | *188.00 FL |
| 13 | 1 | | *REVERSE LIGHT (Supplementary) | Broken | 196.00 F | *196.00 FL |
| 14 | 1 | | *AIR PULLER (\$32, DISCOUNT 20%) (Supplementary) | Broken | 25.60 FS | *25.60 FS |
| F=Fra | anchise | part. S=SpcNe | ett. L=ListItemDisc. | F | | |
| | | | | Sub Total (S\$) | 3,911.60 | 3,089.60 |
| | | - List Item Discount on L Items 0.00/20.00% (S\$) | | | 0.00 | 608.80 |
| | | | | Total Parts (S\$) | 3,911.60 | 2,480.80 |
| | | | Report was unsubmitted | during this print-out. | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--------------------------------------------------------------------------------|---------------|------------|----------|
| Lab | <u>our Items</u> | | | |
| 1 | RENEW REAR BUMPER, REPAIR REAR FENDER LH, REAR END PANEL TAILGATE | New | 2,000.00 | 1,000.00 |
| 2 | SPRAY PAINT FOR REAR BUMPER TOP PANEL, TAILGATE, REAR FENDER LH REAR END PANEL | New | 1,140.00 | 1,140.00 |
| 3 | REMOVE & INSTALL PARKING SENSOR | New | 100.00 | 100.00 |
| 4 | C&C LOGO | New | 40.00 | 40.00 |
| 5 | CHECK WIRING & ELECTRICAL SYSTEM | New | 50.00 | 50.00 |
| 6 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 225.00 | 225.00 |
| 7 | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | New | 120.00 | 0.00 |
| 8 | REPAIR REAR END PANEL (Supplementary) | New | 500.00 | 500.00 |
| 9 | RESPRAY REAR END PANEL (Supplementary) | New | 380.00 | 380.00 |
| | Gross Labo | ur Cost (S\$) | 4,555.00 | 3,435.00 |
| | Report was unsubmitted during thi | s print-out. | | |

< END OF ESTIMATES >