

the removal of the windscreen.

Date:

CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

CITROËN

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240

ESTIMATE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

	lnw	nion N.					GS.	T Reg No	MR-8500111-)
Invoice Name & Address				Owner Name & Vehicle Info					
TAN SUI LIN BLK 18A HOLLAND DRIVE #18-463 SINGAPORE 272018			1 1	Cust No/Name Reg No/Reg Date	/TAN SUI LIN SMJ9395U / 26/03/2019				3 B 16 W
				Date In/Mileage	3M33330 /	0			
				2. Sec. 20 at 20	VF72RHNZWJ437		•		
				Chassis No					
	Contact No	Mahala Azediaza		Engine No	10XK132277926		2 01105	TECU 11	
	Souract 140	Mobile: 97561372		Make/Model	CIT/C3 AIRCRO				
				Colour/Trim	Z4P PASSION F	(ED / 4)	YF AMBI	ANCE SE	KIE
ccount No	Terms	Date/Time Printed	CSE	Operator		WIP No	10 (4.0)		
SM00073	Cash	08/03/2021/ 12:45		442 / CocoLu		16270			
		Description of Goo	ds / Services		Qty	Unit Price	Disc%	A	mount
PNT88000 RENEW RE	AR BUMPER	, REPAIR REAR FENDER	LH. REAR END	PANEL SOO X	2			1000	2000.0
TAILGATE		NET MEN NEMN TENDEN	en, nerm en						
PNT98000	AINT FOD DE	AR BUMPER TOP PANEL,	TATI GATE	PEAR FENDER IN 78	0 X3				1140.0
REAR END		AR BUNFER TO TARLE,	, inituatit, i	CAR TERDER EN 50	5 • •				100.0
PNT88000	TNCTALL D	ARKING SENSOR					**************************************		100.0
SUNDRY	I INSTALL P	ARKING SENSOR							/ 40.0
C&C LOGO)								20.0
SUNDRY Sundry			_ П		л _				
54900099			617	ima	0.170				50.0
	RING & ELE	CTRICAL SYSTEM	\mathcal{S}					1-	225.0
10028901 TO CARRY	OUT DIAGN	OSTIC CHECK USING HI	-SCAN PRO TE						223.
	-SCAN PRO								120 (
WHEELALIG	NMENT	F 1 1/haal Alie							120.0
TO CONDU		rize Full Wheel Alig	nment		1.00	942.00	0.00	1	942.0
OVERRIDE		80			1.00	615.00	0.00		615.0
	OULDING /	CUT (Silver)			1.00	482.00	0.00		482.0
BUMPER B	RACKET	J X MM			1.00	249.00	0.00		249.0 155.0
BUMPER B	RACKET	UX D/G / BR		c/a/01 2 MM	1.00 1.00	155.00 432.00	0.00	/	432.0
	SET LATERA		8 E 41 %	8/3/21, 3.00pm	1.00	418.00	0.00		418.0
BUMPER B		x hn	35 v se	J - J - V	1.00	73.00	0.00	/	73.0
BADGE AS	s her nec		Ctore	CLKK)	1.00	58.00	0.00	_	58.0
BADGE A	nec		Sick		1.00	58.00	0.00		58.0
WING PPO	TECTOR LH	/ CUT	(DA- NOT AL	1.00	188.00	0.00		188.0
MING LKO	TECTOR EN			DO-AMAL			8 #		
				ACIIJ -!					
				PP					
				* / !			1		2 670
		and the second second		0.	Dante				3.0/0.0
Confirm & a	ccepted by	nce notify		s Bil sta	Parts Labour				
	ccepted by			J BIL SM	Labour	u			3,635.0
the Repairer	of the follow	ing:		J Bil Sty	Labour Standard Men Specialist J	ob			3,635.0 0.0 0.0
the Repairer To resurvey be	of the follow efore/after spray maged part(s) d	ing; y painting uring resurvey		J Bil Sty	Labour Standard Men Specialist J Diagnostics	ob Job			3,670.0 3,635.0 0.0 0.0
the Repairer To resurvey be To display dan	of the follow efore/after spray maged part(s) d	ing; y painting uring resurvey		J Bil Sty	Labour Standard Men Specialist J	ob Job s			3,635.0 0.0 0.0

Estimated costs quoted are excluding 657. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50k of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also egree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

Page 1 of 1