

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21003044/BTF3E2**Date:** 11/05/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00072432001

**Claimant Vehicle No :** GBG3504H **Insured Vehicle No :** GBE385P

Date of Loss: 05/03/2021 Nature of Claim: TP Claim No: SNM21D201259/C02/LOWCT

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBG3504H**

Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A) Engine No: YD25419971A

Reg. Date: 21/07/2017 (Man. Year: 2017) Chassis No: JN1MC2E26Z0008283

Colour: White Odometer: 168178 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195 R15

Front Left Side: Dunlop 5 mm Rear Left Side: Tourador 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Tourador 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,886.07	5,959.49	11,926.58	66.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	1,950.00	2,820.00	59.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,656.07</b>	<b>7,909.49</b>	<b>14,746.58</b>	<b>65.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,300.00</b>		
<b>(S\$)</b>	22,656.07	6,300.00	16,356.07	72.19
<b>+ GST 7.00/7.00% (S\$)</b>	1,585.92	441.00	1,144.92	72.19
<b>Nett Amount (S\$)</b>	<b>24,241.99</b>	<b>6,741.00</b>	<b>17,500.99</b>	<b>72.19</b>

**INSPECTION**

Date of Assignment: 10/03/2021

Date Inspected: 10/03/2021 Inspected At: Team Autopro Pte Ltd (Sin Ming)  
160 SIN MING DR  
#01-14 SIN MING AUTO CITY  
SINGAPORE 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 11 May 2021)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG3504H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,195.00 FL	*1,399.20 FL
2	1		*TAILGATE LOGO	Necessary	98.50 FL	*75.00 FL
3	1		*TAILGATE EMBLEM NV350	Necessary	78.00 FL	*78.00 FL
4	1		*TAILGATE EMBLEM URVAN	Necessary	75.68 FL	*75.68 FL
5	1		*TAILGATE OUTER CHROME GARNISH	Broken	449.20 FL	*449.20 FL
6	1		*TAILGATE OUTER HANDLE	No such part	277.10 FL	*- FL
7	2		*TAILGATE HINGE	Not Damaged	250.00 FL	*- FL
8	1		*TAILGATE INNER LOCK	Jammed	289.90 FL	*198.60 FL
9	1		*TAILGATE LOCK ACTUATOR	Not Damaged	381.45 FL	*- FL
10	1		*TAILGATE LOCK STRIKER	Not Damaged	68.10 FL	*- FL
11	2		*TAILGATE HYDRAULIC DAMPER	Not Damaged	442.20 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Torn	282.90 FL	*137.50 FL
13	1		*TAILGATE INNER TRIM BOARD	No such part	204.00 FL	*- FL
14	1		*TAILGATE WINDSCREEN	Broken	1,309.00 FL	*1,309.00 FL
15	1		*TAILGATE WINDSCREEN MOULDING	No such part	182.25 FL	*- FL
16	1		*TAILGATE WINDSCREEN WIPER ARM	Not Damaged	186.30 FL	*- FL
17	1		*TAILGATE WINDSCREEN WIPER GARNISH	Not Damaged	123.50 FL	*- FL
18	2		*REAR NUMBER PLATE LAMP	Not Damaged	116.00 FL	*- FL
19	1		*REAR WING MIRROR	Not Damaged	332.00 FL	*- FL
20	1		*REAR BUMPER	Dented	641.00 FL	*641.00 FL
21	2		*REAR BUMPER SIDE RETAINER	Not Necessary	244.20 FL	*- FL
22	4		*REAR BUMPER LOWER BRACKET	No such part	337.00 FL	*- FL
23	1		*REAR BUMPER STEP PANEL	Dented	398.10 FL	*346.00 FL
24	1		*REAR END PANEL CENTRE	Dented	581.45 FL	*581.45 FL
25	2		*REAR END PANEL SIDE	Not Damaged	575.44 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Damaged	262.80 FL	*- FL
27	1		*SPARE TYRE BRACKET	Not Damaged	269.30 FL	*- FL
28	1		*REAR FLOOR PANEL	Not Damaged	3,204.00 FL	*- FL
29	1		*TAILLAMP	N/S Broken	962.00 FL	*224.80 FL
30	1		*TAILGATE WINDSCREEN WIPER MOTOR	Not Damaged	428.60 FL	*- FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE SEALANT	Necessary	100.00 FS	*60.00 FS
33	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	120.00 FS	*40.00 FS
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
37	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	60.00 FS	*- FS
38	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*20.00 FS
39	1		*TAILGATE STICKER 8 PAX	Necessary	30.00 FS	*20.00 FS
40	1		*TAILGATE STICKER	Necessary	380.00 FS	*180.00 FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*REAR BUMPER STEP PANEL SEALANT	No such part	100.00 FS	*- FS
43	2		*REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
44	1		*REAR END PANEL CENTRE SEALANT	Necessary	100.00 FS	*40.00 FS
45	2		*REAR END PANEL SIDE SEALANT	Not Necessary	200.00 FS	*- FS
46	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FLOOR BED TOP BOARD	Not Damaged	1,600.00 FS	*- FS
48	1		*TAILLAMP SEAL	N/S Necessary	120.00 FS	*30.00 FS
49	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
50	1		*REAR NUMBER PLATE	Dented	80.00 FS	*40.00 FS
51	1		*TAILGATE THIRD BRAKE LIGHT	Cracked	184.00 FL	*184.00 FL
52	1		*TAILGATE THIRD BRAKE LIGHT SEAL	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,428.97</b>	<b>6,529.43</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,542.90	569.94
<b>Total Parts (\$\$)</b>	<b>17,886.07</b>	<b>5,959.49</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R TAILGATE COMPONENT	New	200.00	80.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R REAR WINDSCREEN	New	250.00	120.00
4	R&R REAR FLOOR BED TOP BOARD	New	300.00	0.00
5	CONDUCT WATER LEAK TEST	New	120.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEATING	New	1,600.00	800.00
8	RUST PROOFING	New	200.00	60.00
9	SPRAY PAINTING	New	1,600.00	800.00
10	CHECK WIRING	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,770.00</b>	<b>1,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >