11/17/21, 3:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003046/T1GA3Q2

17/11/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070115513 **Claimant Vehicle** SHA9832G Insured Vehicle No: SFW3322J

No:

Date of Loss: 08/03/2021 Nature of Claim: TP Claim No: 4494910588SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA9832G

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) Engine No: G4LEKU385147

Reg. Date: 14/11/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU182767

Colour: Odometer: 121755 km Yellow

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,155.12	55.00	1,100.12	95.24
Miscellaneous Items		0.00	0.00	0.00	
Labour		820.00	630.00	190.00	23.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,975.12	685.00	1,290.12	65.32
	+ GST 7.00/7.00% (S\$)	138.26	47.95	90.31	65.32
	Nett Amount (S\$)	2,113.38	732.95	1,380.43	65.32
	+ Loss of Use (3.0 x	S\$50.00/day) (S\$)	150.00		
	+ Car Rental (3.0 x S	\$125.19/day) (S\$)	375.57		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,260.52		
	Global Su	m Settlement (S\$)	1,250.00		

INSPECTION

Date of Assignment: 08/03/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 09/03/2021 Inspected At:

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID Chong Pui Lin Adjuster: Manager:

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CTR MOULDING	Repair	451.25 FL	*- FL
3	1		*REAR BUMPER LWR MOULDING	Not Necessary	155.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
6	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
7	1		*REAR NO PLATE W/TRIM COVER	Cracked	55.00 FS	*55.00 FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.	Sub Total (S\$)	1,372.65	55.00
			- List Item Discount o	on L Items 20.00/20.00% (S\$)	217.53	0.00
				Total Parts (S\$)	1,155.12	55.00
			Report was unsubmitted	I during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	30.00
		Gross Labour Cost (S\$)	820.00	630.00
	R	Report was unsubmitted during this print-out.		

< END OF ESTIMATES >