

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003047/KNY3E2**Date:** 30/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00083642001	
Claimant Vehicle No :	SMJ987X	Insured Vehicle No :	GBH7171C	
Date of Loss:	04/03/2021	Nature of Claim:	TP	Claim No: SNM21D201280/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ987X		Engine No:	CDL026143
Make & Model:	VOLKSWAGEN GOLF R, 2.0 5DR 5K1RX7 (A)		Chassis No:	WVWZZZ1KZAW318708
Reg. Date:	07/05/2010 (Man. Year: 2010)		Odometer:	186433 km
Colour:	White			
Engine Capacity:	1984 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,282.91	2,171.04	2,111.87	49.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	460.00	520.00	53.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,262.91	2,631.04	2,631.87	50.01
+ GST 7.00/7.00% (\$\$)	368.40	184.17	184.23	50.01
Nett Amount (\$\$)	5,631.31	2,815.21	2,816.10	50.01

INSPECTION

Date of Assignment:	09/03/2021	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Date Inspected:	09/03/2021 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,560.96 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2022)

Parts: 144 VOLKSWAGEN GOLF R 2.0 5DR 5K1RX7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ987X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	2,293.15 FL	*2,293.15 FL
2	1		*REAR BUMPER LOWER GARNISH LH	* Check	999.35 FL	*- FL
3	1		*REAR BUMPER LOWER GARNISH REFLECTOR LH	Cracked	66.90 FL	*66.90 FL
4	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	93.50 FL	*- FL
5	1		*REAR BUMPER CENTRE RETAINER	Serviceable	112.45 FL	*- FL
6	12		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*REAR BUMPER REINFORCEMENT	* Check	606.05 FL	*- FL
8	2		*REVERSE SENSOR LH INNER & OUTER	Serviceable	389.50 FL	*- FL
9	4		*REVERSE SENSOR HOLDER	* Check	129.00 FL	*- FL
10	1		*REAR VIEW CAMERA (NPA)	Serviceable	0.00 FS	*- FS
11	1		*REAR BUMPER LOWER GARNISH COVER LH	* Check	0.00 FS	*- FS
12	1		*NUMBER PLATE	Scratched	35.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,754.90	2,410.05
- List Item Discount on L Items 10.00/10.00% (\$\$)	471.99	239.01
Total Parts (\$\$)	4,282.91	2,171.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL / REPLACE REAR VIEW CAMERA }	New	60.00	60.00
2	TO REMOVE AND REINSTALL / REPLACE REAR BUMPER SENSORS }	New	60.00	0.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, REAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	400.00	200.00
5	TO SPRAY REAR BUMPER, END PANEL	New	400.00	200.00
Gross Labour Cost (\$)			980.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >