

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG21003050/AGA3Q2

Date:

20/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900121511

Claimant Vehicle No : PA7882E**Insured Vehicle No :**

SMM9584A

Date of Loss: 08/03/2021

Nature of Claim:

TP

Claim No:

3051829955SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PA7882E**

Make & Model: TOYOTA HIACE, 3.0 COMMUTER GL (A)

Engine No:

1KD1836146

Reg. Date: 08/09/2008 (Man. Year: 2008)

Chassis No:

KDH2230004342

Colour: Silver

Odometer:

417715 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Windforce 6 mm

Rear Left Side:

Windforce 6 mm

Front Right Side: Windforce 6 mm

Rear Right Side:

Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,195.47	2,760.63	2,434.84	46.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,430.00	330.00	18.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,955.47	4,190.63	2,764.84	39.75
Approved Total (Overridden) (S\$)		3,300.00		

(S\$)	6,955.47	3,300.00	3,655.47	52.56
+ GST 7.00/7.00% (S\$)	486.88	231.00	255.88	52.56
Nett Amount (S\$)	7,442.35	3,531.00	3,911.35	52.56
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 09/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

RYDER AUTO PTE LTD
 2 KAKI BUKIT AVE 2
 #02-19/22 KAKI BUKIT AUTOHUB
 SINGAPORE 417921

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	492.57 FL	*492.57 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
4	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	362.70 FL	*55.00 FL
5	1		*REAR TAIL GATE	Dented	2,810.86 FL	*2,150.00 FL
6	1		*REAR TAIL GATE CHROME MOULDING	Not Necessary	486.20 FL	*- FL
7	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	67.60 FL	*67.60 FL
8	1		*REAR TAILGATE 70KMPH EMBLEM	Necessary	15.00 FS	*15.00 FS
9	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
10	1		*REAR WINDSCREEN MOULDING	Necessary	240.00 FS	*165.00 FS
11	1		*REAR TAIL GATE WEATHERSTRIP	Not Necessary	420.00 FL	*- FL
12	1		*REAR END PANEL	Repair	495.17 FL	*- FL
13	1		*REAR END PANEL INNER TRIM	Not Necessary	292.60 FL	*- FL
14	8		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	32.00 FS	*- FS
15	1		*REAR LOCK UPPER	Damaged	543.60 FL	*289.00 FL
16	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,688.30	3,524.17
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,492.83	763.54
Total Parts (\$\$)	5,195.47	2,760.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	800.00	600.00
2	TO SPRAY PAINTING	New	600.00	600.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	180.00	120.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO RE-SEAL ANTI RUST	New	80.00	80.00
Gross Labour Cost (S\$)			1,760.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >