

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003061/UPA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492385

Claimant
Vehicle No : SLC1865G **Insured Vehicle No :** SLJ2928R

Date of Loss: 25/02/2021 Nature of Claim: TP Claim No: 2194938344SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC1865G	Engine No:	D4HBGH265709
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAPH81BMG5202034
Reg. Date:	04/05/2016 (Man. Year: 2016)	Odometer:	80413 km
Colour:	Brown		
Engine Capacity:	2199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	PETLAS 8 mm	Rear Left Side:	PETLAS 8 mm
Front Right Side:	PETLAS 8 mm	Rear Right Side:	PETLAS 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,677.10	1,523.20	1,153.90	43.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	620.00	870.00	58.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,167.10	2,143.20	2,023.90	48.57
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	4,167.10	1,700.00	2,467.10	59.20
+ GST 7.00/7.00% (\$\$)	291.70	119.00	172.70	59.20
Nett Amount (\$\$)	4,458.80	1,819.00	2,639.80	59.20
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
Nett Liability (\$\$)		1,999.00		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 11/03/2021 Inspected At:

Revo Performance Pte Ltd (HQ)
BLK 1 KAKI BUKIT AVE 6 AUTOBAY
#02-51
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	869.00 FL	*645.00 FL
2	2		*FRONT BUMPER SENSOR	Not Necessary	596.00 FL	*- FL
3	1		*FRONT BUMPER INNER SPONGE	Not Necessary	145.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Deformed / Cut	360.00 FL	*360.00 FL
5	1		*FRONT BUMPER LOWER GRILLE GARNISH	Deformed	386.00 FL	*386.00 FL
6	1		*FRONT BUMPER LOWER PAD	Deformed	426.00 FL	*220.00 FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	48.00 FL	*- FL
8	1		*FRONT NUMBER PLATE SUPPORT	Bent	89.00 FL	*37.00 FL
9	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,969.00	1,688.00
- List Item Discount on L Items 10.00/10.00% (S\$)	291.90	164.80
Total Parts (S\$)	2,677.10	1,523.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	250.00
2	CHECK WIRING	New	60.00	20.00
3	SPRAY PAINTING	New	680.00	350.00
Gross Labour Cost (S\$)			1,490.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >