

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21003063/APA3Q2**Date:** 30/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070102299
Claimant Vehicle No :	SJX9955R	Insured Vehicle No :	SMT3943A
Date of Loss:	14/02/2021	Nature of Claim:	TP
		Claim No:	1703627891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX9955R	Engine No:	CHZC29924
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V7KA080957
Reg. Date:	30/08/2019 (Man. Year: 2019)	Odometer:	19979 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,847.00	1,744.80	2,102.20	54.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,269.00	3,266.80	3,002.20	47.89
+ GST 7.00/7.00% (S\$)	438.83	228.68	210.15	47.89

Nett Amount (S\$)	6,707.83	3,495.48	3,212.35	47.89
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,797.48		

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 09/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS	
3	2		*REAR BUMPER GUIDE SECTION LH/RH	Not Necessary	32.00 FS	*- FS	
4	1		*REAR BUMPER LOWER SPOILER	Cut	237.00 FS	*189.60 FS	
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS	
6	1		*REAR BUMPER IMPACT BAR	Not Necessary	603.00 FS	*- FS	
7	2		*REAR BUMPER IMPACT BAR BRACKET LH/RH	Not Necessary	54.00 FS	*- FS	
8	2		*REAR PARKING SENSOR INNER /OUTER	Not Necessary	488.00 FS	*- FS	
9	4		*REAR PARKING SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS	
10	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS	
					Total Parts (S\$)	3,847.00	1,744.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (S\$)	2,422.00
				1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >