

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003068/ABA3Q2
Date: 10/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800032721
Claimant Vehicle No :	SMR1418Z	Insured Vehicle No :	SLX5376P
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	9847893229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1418Z		
Make & Model:	SUZUKI SWIFT, 1.4 GL (M)	Engine No:	K14C1209366
Reg. Date:	20/12/2019 (Man. Year: 2019)	Chassis No:	ZC33S117925
Colour:	Black	Odometer:	12265 km
Engine Capacity:	1371 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/45 R17	Rear Tyre Size:	195/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,533.87	7,223.69	4,310.18	37.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,500.00	4,660.00	4,840.00	50.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	21,033.87	11,883.69	9,150.18	43.50
	+ Car Rental (23.0 x S\$100.00/day) (S\$)	2,300.00		
	+ Doc/Search Fee (S\$)	7.45		

Nett Liability (S\$)**14,191.14**INSPECTION

Date of Assignment: 05/03/2021

Date Inspected: 05/03/2021

Estimated Period of Repair: 21.0 days

Inspected At:

Sin Hwee Motor Pte Ltd (HQ)
Blk 3023A, Ubi Road 1, #01-59
Singapore 408717**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	984.30 FL	*984.30 FL
2	1		*TAILGATE LOCK	Damaged	159.15 FL	*159.15 FL
3	1		*TAILGATE SWITCH	Damaged	175.25 FL	*175.25 FL
4	1		*TAILGATE SWITCH CASING	Cracked	37.55 FL	*37.55 FL
5	1		*TAILGATE INNER TRIM	Cracked	265.58 FL	*265.58 FL
6	1		*WINDSCREEN	Shattered	549.00 FL	*549.00 FL
7	1		*WINDSCREEN INNER SEAL (1 SET)	Necessary	95.10 FL	*95.10 FL
8	1		*CENTER LOGO	Necessary	26.75 FL	*26.75 FL
9	1		*SWIFT LOGO	Necessary	29.10 FL	*29.10 FL
10	1		*SPORT LOGO	Necessary	35.11 FL	*35.11 FL
11	2		*BOOTLID DAMPER	Not Necessary	365.10 FL	*- FL
12	1		*WIPER MOTOR	Not Necessary	427.78 FL	*- FL
13	1		*WIPER BLADE	Not Necessary	38.90 FL	*- FL
14	1		*WIPER ARM	Not Necessary	73.44 FL	*- FL
15	1		*END PANEL	Distorted	455.82 FL	*455.82 FL
16	1		*END PANEL TOP GARNISH	Cracked	98.10 FL	*98.10 FL
17	2		*END PANEL VENTILATION OULET	Deformed	57.90 FL	*57.90 FL
18	2		*END PANEL INNER GARNISH	Deformed	79.08 FL	*79.08 FL
19	1		*FLOORBOARD PANEL	Repair	490.55 FL	*- FL
20	1		*WEATHERSTRIP	Cut	87.51 FL	*87.51 FL
21	1		*REAR FENDER R/H	Buckled	552.08 FL	*552.08 FL
22	1		*REAR FENDER INNER TRIM R/H	Deformed	293.77 FL	*293.77 FL
23	1		*REAR FENDER INNER TRIM L/H	Deformed	293.77 FL	*293.77 FL
24	1		*TAILLAMP L/H	Cracked	798.55 FL	*495.00 FL
25	1		*TAILLAMP R/H	Cracked	798.55 FL	*495.00 FL
26	2		*TAILLAMP PANEL	Repair	357.04 FL	*- FL
27	1		*REAR BUMPER	Distorted	972.62 FL	*752.00 FL
28	1		*REAR BUMPER LOWER SPOILER L/H	Not Necessary	65.77 FL	*- FL
29	1		*REAR BUMPER LOWER SPOILER R/H	Deformed	65.77 FL	*65.77 FL
30	1		*REAR BUMPER LAMP	Cut	84.58 FL	*84.58 FL
31	2		*BUMPER SIDE RETAINER	Not Necessary	59.80 FL	*- FL
32	2		*NUMBER PLATE LAMP	Cracked	149.70 FL	*149.70 FL
33	1		*REAR FENDER INNER COVER	Torn	128.44 FL	*128.44 FL
34	1		*REAR SPEAKER TRIM	Deformed	285.00 FL	*285.00 FL
35	1		*TAILGATE SENSOR	Damaged	78.44 FL	*78.44 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SPARE TYRE BOARD	Deformed	185.11 FL	*185.11 FL
37	1		*EXHAUST INSULATOR	Crumpled	148.70 FL	*148.70 FL
38	1		*REAR FENDER INNER TRIM COVER -JACK COVER	Deformed	85.21 FL	*85.21 FL
39	10		*BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
40	1		*SET NUMBER AND HOLDER	Cracked	90.00 FS	*60.00 FS
41	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
42	1		*REAR EXHAUST PIPE -HKS (LOCAL REPAIR)	Bent	1,950.00 FS	*200.00 FS
43	1		*SOLAR FLIM	Necessary	250.00 FS	*200.00 FS
44	1		*SET REVERSE CAMERA	Damaged	480.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,023.97	8,307.87
- List Item Discount on L Items 15.00/15.00% (\$)	1,490.10	1,084.18
Total Parts (\$)	11,533.87	7,223.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING SERVICE	New	80.00	60.00
2	TO INSTALL AND CALIBRATE REVERSE SENSOR	New	80.00	50.00
3	TO SUPPLY FITTINGS AND INSTALL REVERSE CAMERA	New	150.00	50.00
4	TO INSTALL REAR WIND SCREEN	New	200.00	120.00
5	TO SUPPLY WINDSCREEN SEALANT	New	80.00	60.00
6	TO DISMOUNT AND MOUNT REAR SEAT ,INNER TRIMS ,CARPET AND ROOF LINING TO FACILITATE REPAIR WORK	New	450.00	180.00
7	TO DISMOUNT AND MOUNT PETROL TANK TO FACILITATE REPAIR WORK	New	280.00	0.00
8	TO DISMOUNT AND ALIGN REAR EXHAUST PIPE	New	150.00	100.00
9	COMPUTER ALIGNMENT	New	180.00	0.00
10	TO TRANSFER TAILGATE MECHANISMS ,FITTINGS AND TRIMS AND NEW TAILGATE	New	250.00	80.00
11	TO MOUNT VEHICLE ON CAR O LINER BENCH AND SET UP REPAIR TOOLS	New	350.00	250.00
12	TO REPLACE REAR END PANEL ,FLOORBOARD PANEL AND REAR FENDER INCLUDE KNOCKING ,CUTTING AND WELDING TO REPLACE ,INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	4,200.00	2,000.00
13	TO SPRAY PAINT REAR FENDERS ,TAILGATE ,BUMPER ,END PANEL ,AND FLOORBOARD	New	2,500.00	1,600.00
14	TO SUPPLY AND TUFF KOTE	New	350.00	80.00
15	TO CARRY OUT WIRE CHECKING	New	200.00	30.00
Gross Labour Cost (S\$)			9,500.00	4,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >