

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003070/R1GS3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210021837
Claimant Vehicle No :	SKJ3013K	Insured Vehicle No :	SLR3122A
Date of Loss:	06/03/2021	Nature of Claim:	TP
		Claim No:	8966613866SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ3013K	Engine No:	DED035923
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI (A)	Chassis No:	WVWZZZ7NZLV015647
Reg. Date:	24/09/2020 (Man. Year: 2020)	Odometer:	9080 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,699.23	7,755.44	1,943.79	20.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,830.00	4,550.00	3,280.00	41.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,529.23	12,305.44	5,223.79	29.80
+ GST 7.00/7.00% (S\$)	1,227.05	861.38	365.67	29.80

Nett Amount (S\$)	18,756.28	13,166.82	5,589.46	29.80
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Deformed	1,746.32 FS	*1,746.32 FS
2	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	33.69 FS	*- FS
3	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	*Check	33.69 FS	*- FS
4	1		*SUPPORT PART BUMPER INNER BRACKET RH	*Check	29.14 FS	*- FS
5	1		*COOLING AIR GRILL SATIN B FOG LAMP GRILLE RH	Scratched	176.03 FS	*176.03 FS
6	1		*PROTECTIVE STRIP BRIGHT C FOG LAMP GRILLE CHROM RH	*Check	105.16 FS	*- FS
7	1		*PRESSURE CYLINDER NOZZLE CYLINDER RH	*Check	190.17 FS	*- FS
8	1		*JET CARRIER WITH JET NOZZLE RH	*Check	45.99 FS	*- FS
9	1		*CAP PRIMED NOZZLE CAP RH	Scratched	62.12 FS	*62.12 FS
10	1		*HEADLAMPS FOR CURVE LIGHT H/LAMP RH	Scratched	2,333.51 FS	*2,333.51 FS
11	1		*FENDER FENDER RH	Bent	797.40 FS	*797.40 FS
12	1		*CROSS SUPPORT FENDER BRACKET RH	Necessary	46.93 FS	*46.93 FS
13	1		*WHEELHOUSE LINER FENDER LINER RH	Deformed	141.98 FS	*141.98 FS
14	6		*EXPANDING NUT	Necessary	10.50 FS	*10.50 FS
15	1		*ALLOY WHEEL GREY-METALLIC	Scratched	2,437.23 FS	*2,437.23 FS
16	1		*RUBBER VALVE	Necessary	3.42 FS	*3.42 FS
17	1		*WHEEL BEARING WITH MOUNTI	*Check	595.86 FS	*- FS
18	1		*WHEEL BEARING HOUSING	*Check	700.37 FS	*- FS
19	1		*GUIDE JOINT	*Check	146.84 FS	*- FS
20	1		*OVAL HEXAGON SOCKET HEAD	*Check	7.40 FS	*- FS
21	1		*SHOULDERED HEX NUT SELF	*Check	3.11 FS	*- FS
22	1		*SHOULDERED HEX NUT	*Check	5.87 FS	*- FS
23	3		*SHOULDERED HEX NUT	*Check	8.28 FS	*- FS
24	1		*DEGREASER CLEANER 500ML	*Check	38.22 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,699.23	7,755.44
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	WHEEL ALIGNMENT	New	360.00	360.00
5	R&R RIM & BALANCE	New	50.00	50.00
6	LABOUR	New	3,360.00	1,680.00
7	SPRAY PAINT	New	3,200.00	1,600.00
Gross Labour Cost (S\$)			7,830.00	4,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >