

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003071/UGS3Q2
Date: 18/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700059562
Claimant Vehicle No :	SLH8033T	Insured Vehicle No :	SLS6640X
Date of Loss:	06/03/2021	Nature of Claim:	TP
		Claim No:	2851727416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH8033T		
Make & Model:	TOYOTA CAMRY, 2.4 ABS AIRBAG (A)	Engine No:	2AZE057787
Reg. Date:	18/12/2007 (Man. Year: 2007)	Chassis No:	MR053BK4007019178
Colour:	Grey	Odometer:	226854 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,427.72	680.90	746.82	52.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	870.00	820.00	48.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,117.72	1,550.90	1,566.82	50.26
Approved Total (Overridden) (S\$)		1,200.00		

(S\$)	3,117.72	1,200.00	1,917.72	61.51
+ GST 7.00/7.00% (S\$)	218.24	84.00	134.24	61.51
Nett Amount (S\$)	3,335.96	1,284.00	2,051.96	61.51
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		1,584.00		

INSPECTION

Date of Assignment: 14/04/2021

Date Inspected: 14/04/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	629.80 FL	*581.20 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	420.10 FL	*- FL
4	1		*REAR BUMPER REFLECTOR	Not Necessary	54.80 FL	*- FL
5	1		*REAR BUMPER RH RETAINER	Not Necessary	55.30 FL	*- FL
6	1		*BOOTLID CAMRY EMBLEM	Not Necessary	49.90 FL	*- FL
7	1		*BOOTLID LOGO	Not Necessary	66.80 FL	*- FL
8	1		*BOOTLID 2.4 EMBLEM	Not Necessary	39.60 FL	*- FL
9	1		*SET REAR REVERSE SENSOR	Shorted	395.50 FS	*200.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,771.80
					- List Item Discount on L Items 25.00/25.00% (\$\$)	344.08
					Total Parts (\$\$)	1,427.72
						841.20
						160.30
						680.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REAR SENSOR	New	100.00	50.00
2	TUFF COAT	New	100.00	0.00
3	TO REMOVE ,RENEW PARTS ,REPAIR BOOTLID & END PANEL	New	680.00	300.00
4	WIRING CHECK (REAR)	New	30.00	20.00
5	SPRAY PAINTING (REAR)	New	780.00	500.00
Gross Labour Cost (S\$)			1,690.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >