



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 4996T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LIGHT L/H	SCRATCHED	1,373.00	1,373.00
1	FRONT FENDER L/H	CRUMPLED	650.00	650.00
1	FRONT PANEL LINER	CRUMPLED	280.00	149.30
1	FRONT LEFT DOOR L/H	CRUMPLED	1,458.00	1,458.00
1	FRONT BUMPER	CRUMPLED	890.00	890.00
1	BUMPER RETAINER L/H	BROKEN	66.00	66.00
1	BUMPER BRACKET	BROKEN	74.00	74.00
1	SENSOR L/H	SHORTED	148.00	148.00
	LESS 10% DISCOUNT		-	-480.83
			4,939.00	4,327.47
	<u>LABOUR</u>			
	SPRAY PAINT.		600.00	600.00
	LABOUR.		550.00	550.00
			1,150.00	1,150.00
	GRAND TOTAL		6,089.00	5,477.47
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)			4,400.00

Report Ref No. CS3/LPC21002196/Qqf3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.