

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21003078/KTD3N2**Date:** 06/10/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001621699
Claimant Vehicle No :	SJQ2983S	Insured Vehicle No :	SLK2554E
Date of Loss:	07/03/2021	Nature of Claim:	TP
		Claim No:	254288

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ2983S	Engine No:	L15B4405002
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11205002
Reg. Date:	23/05/2017 (Man. Year: 2016)	Odometer:	116531 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,214.76	7,268.68	3,946.08	35.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,960.00	5,190.00	770.00	12.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,174.76	12,458.68	4,716.08	27.46
+ GST 7.00/7.00% (S\$)	1,202.23	872.11	330.12	27.46
Nett Amount (S\$)	18,376.99	13,330.79	5,046.20	27.46

INSPECTION

Date of Assignment:	08/03/2021	
Date Inspected:	09/03/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	18.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ2983S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Bent	532.10 FL	*532.10 FL
2	1	*REAR BUMPER LH REFLECTORS	N/s Cracked/ O/s Serviceable	297.00 FL	*148.50 FL
3	6	*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
4	1	*REAR BUMPER LH SIDE PAD	Buckled	195.00 FL	*195.00 FL
5	1	*REAR WINDSCREEN GLASS MOULDING	Necessary	118.50 FL	*118.50 FL
6	1	*REAR TAILGATE	Bent	997.00 FL	*997.00 FL
7	1	*TAILGATE EMBLEM (VEZEL)	Necessary	45.30 FL	*45.30 FL
8	1	*TAILGATE INNER LOCK	Jammed	96.20 FL	*96.20 FL
9	1	*TAILGATE INNER RUBBER	Cut	101.70 FL	*101.70 FL
10	1	*TAILGATE OUTER GARNISH	Mtg Cracked	225.70 FL	*225.70 FL
11	1	*TAILGATE REFLECTORS	N/s Cut/ O/s Serviceable	553.00 FL	*276.50 FL
12	1	*TAILLAMPS	N/s Cut/ O/s Serviceable	964.80 FL	*482.40 FL
13	1	*REAR END PANEL INNER TOP GARNISH	Dented	98.00 FL	*98.00 FL
14	3	*REAR END PANEL CLIPS	Necessary	11.70 FL	*11.70 FL
15	1	*REAR SPARE TYRE PANEL	Bent	787.50 FL	*787.50 FL
16	1	*REAR SPARE TYRE PANEL TOP TOOL BOX	Cracked	142.80 FL	*142.80 FL
17	1	*REAR SPARE TYRE PANEL TOP BOARD	Buckled	135.00 FL	*135.00 FL
18	1	*REAR SPARE TYRE PANEL UNDER COVER	Distorted	190.10 FL	*190.10 FL
19	6	*REAR SPARE TYRE PANEL UNDER COVER CLIPS	Necessary	22.80 FL	*22.80 FL
20	1	*TAILGATE INNER BOARD	Buckled	153.40 FL	*153.40 FL
21	1	*REAR END PANEL	Bent	411.90 FL	*411.90 FL
22	1	*REAR SMART KEY SENSOR	Cracked	80.50 FL	*80.50 FL
23	1	*REAR EXHAUST PIPE	Bent	528.10 FL	*528.10 FL
24	2	*REAR EXHAUST PIPE BUSHES	Torn	31.40 FL	*31.40 FL
25	1	*REAR EXHAUST TOP HEAT SEAL	Bent	49.10 FL	*49.10 FL
26	1	*CENTRE EXHAUST PIPE	Bent	680.10 FL	*680.10 FL
27	1	*FRONT BUMPER	Buckled	549.80 FL	*549.80 FL
28	1	*FRONT BUMPER LH SIDE RETAINER	Distorted	15.70 FL	*15.70 FL
29	1	*FRONT BUMPER REINFORCEMENT	Bent	321.00 FL	*321.00 FL
30	2	*FRONT BUMPER REINFORCEMENT TOP GARNISHS	Serviceable	34.80 FL	*- FL
31	2	*REAR FENDER WHEEL ARC GARNISHS	Buckled	300.60 FL	*300.60 FL
32	1	*FRONT GRILLE TOP COVER	Serviceable	54.00 FL	*- FL
33	1	*FRONT GRILLE LOGO	Not Necessary	24.70 FL	*- FL
34	4	*FRONT GRILLE CLIPS	Not Necessary	15.20 FL	*- FL
35	6	*FRONT BUMPER CLIPS	Necessary	22.80 FL	*22.80 FL
36	1	*BONNET	Bent	892.50 FL	*892.50 FL
37	2	*HEADLAMPS	Serviceable	3,847.00 FL	*- FL
38	2	*HEADLAMP LOWER GARNISHS	Cracked	75.00 FL	*75.00 FL
39	1	*OUTSIDE TEMPERATURE SWITCH	Serviceable	49.50 FL	*- FL
40	1	*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
41	1	*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
42	1	*FRONT NUMBER PLATE	Dented	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,949.70 9,017.10

Report was unsubmitted during this print-out.

10/6/21, 9:26 AM			Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's Amount
			- List Item Discount on L Items 20.00/20.00% (S\$)		2,734.94 1,748.42
			Total Parts (S\$)	11,214.76	7,268.68
Report was unsubmitted during this print-out.					

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX SEAT,CARPET,GARNISH,ETC	New	120.00	120.00
3	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR TAILGATE,REAR WIPER,REAR LOCK ASSY,TO STRAIGHTEN,KNOCK & REPAIR REAR BOTH CHASSISS,CUT,WELD & RENEW REAR SPARE TYRE COMPARTMENT,REAR END PANEL,KNOCK & REPAIR REAR BOTH FENDERS & REALIGN THE STRUCTURE THE SAME	New	2,200.00	2,000.00
4	REMOVE & REFIX REAR UNDER CARRIAGE	New	250.00	0.00
5	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	New	120.00	100.00
6	PUTTY & RESPRAY ON TAILGATE,REAR BOTH FENDERS,BOTH TOP ROOF SIDE PANELS,REAR SPARE TYRE COMPARTMENT,REAR PANEL & REAR AFFECTED AREAS	New	1,300.00	1,200.00
7	PANEL BEATING ON FRONT PORTION	New	600.00	500.00
8	PUTTY & RESPRAY ON BONNET,FRT SUPPORT PANEL,FRT BUMPER REINFORCEMENT	New	800.00	700.00
9	TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN	New	250.00	250.00
10	REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	New	60.00	60.00
11	RUSTPROOFING	New	60.00	60.00
12	REMOVE & REFIX FUEL TANK	New	80.00	80.00
Gross Labour Cost (S\$)			5,960.00	5,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >