#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21003079/GTF3E2

29/03/2021 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070125657 **Claimant Vehicle** FBL8524R Insured Vehicle No: SMU6923H

No:

Date of Loss: 07/12/2020 Nature of Claim: TP Claim No: 4831747708SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **FBL8524R** 

Make & Model: YAMAHA XABRE, 150cc TFX150 Engine No: G3G8E0031513

Reg. Date: 17/04/2017 (Man. Year: 2017) Chassis No: MH3RG3710HK024719

Colour: Odometer: 0 km Black

**Engine Capacity:** 150 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 140/70 R17 Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm

Front Right Side: Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 05/03/2021

Hua Ho Trading (HQ)

Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Date Inspected: 09/03/2021 Inspected At:

Park C

Singapore 539187

Estimated Period of Repair: 0.0 days

XING GUO QIANG Adjuster: DENISE TAY KWEE CHENG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

Market Value: \$8,400.00
OMV: \$2,683.00
PARF Rebate (1): \$0.00
Quota Premium Paid: \$7,589.00
COE Rebate (2): \$4,631.00
Total Rebate (1) + (2) = : \$4,631.00

The total amount incurred will be Market Value \$8,400.00 minus Total Rebate \$4,631.00 = \$3,769.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## **REPAIR DETAILS**

# **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >