

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003080/KBA3Q2
Date: 17/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070117345
Claimant Vehicle No :	SMC6001M	Insured Vehicle No :	SKB606L
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	3040755292SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6001M	Engine No:	G4FGJU219162
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU714847
Reg. Date:	12/07/2018 (Man. Year: 2018)	Odometer:	37890 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,353.68	977.60	2,376.08	70.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,090.00	770.00	41.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,213.68	2,067.60	3,146.08	60.34
Approved Total (Overridden) (S\$)		1,600.00		

(S\$)	5,213.68	1,600.00	3,613.68	69.31
+ GST 7.00/7.00% (S\$)	364.96	112.00	252.96	69.31
Nett Amount (S\$)	5,578.64	1,712.00	3,866.64	69.31
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	1,892.00 FL	*- FL
2	1		*REAR FENDER COWLING FRT RH	Serviceable	60.40 FL	*- FL
3	1		*REAR FENDER COWLING RR RH	Serviceable	56.00 FL	*- FL
4	8		*REAR FENDER COWLING CLIPS	Not Necessary	8.00 FL	*- FL
5	1		*REAR FENDER MUDFLAP RH	Cut	23.00 FL	*23.00 FL
6	1		*REAR WINDSCREEN MOULDING	Not Necessary	74.20 FL	*- FL
7	1		*REAR BUMPER	Buckled / Dented	459.40 FL	*459.40 FL
8	1		*REAR BUMPER LOWER COVER	Serviceable	250.10 FL	*- FL
9	1		*REAR BUMPER REFLECTOR RH	Serviceable	40.80 FL	*- FL
10	1		*REAR BUMPER SIDE RETAINER RH	Distorted	44.30 FL	*44.30 FL
11	12		*REAR BUMPER CLIPS	Necessary	24.00 FL	*24.00 FL
12	1		*REAR BUMPER GUARD RH	Serviceable	15.00 FL	*- FL
13	1		*REAR WHEEL CAP RH	Serviceable	44.60 FL	*- FL
14	1		*REAR WHEEL BEARING W HUB RH	*Check	454.00 FL	*- FL
15	1		*SPORTS RIM RHR (R15)	Dented	671.30 FL	*671.30 FL
16	1		*TYRE RHR (NPA)	Serviceable	0.00 FS	*- FS
17	1		*INNER SEAL	Not Necessary	20.00 FS	*- FS
18	1		*WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,177.10	1,222.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	823.42	244.40
Total Parts (\$\$)	3,353.68	977.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	0.00
3	TO REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	80.00
4	TO DISMANTLE REPLACE AND REINSTALL UNDERCARRIAGE	New	60.00	0.00
5	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
6	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
7	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD REAR FENDER LH .TO KNOCK & REPAIR REAR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	700.00	500.00
8	TO SPRAY REAR FENDER RH ,REAR BUMPER	New	600.00	400.00
Gross Labour Cost (S\$)			1,860.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >