

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19012978/R1QD3E2-1

**Date:** 16/03/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29003524

**Claimant Vehicle No :** GBJ2817X

**Insured Vehicle No :** GBE596Y

Date of Loss: 20/07/2019

Nature of Claim: TP

Claim No: 600665

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ2817X**

Make & Model: TOYOTA HIACE, 3.0 (A)

Engine No: 1KD2846629

Reg. Date: 11/03/2019 (Man. Year: 2019)

Chassis No: JTFHT02P600248409

Colour: Grey

Odometer: 26240 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,903.55	3,710.94	2,192.61	37.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,730.00	1,230.00	41.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,863.55</b>	<b>5,440.94</b>	<b>3,422.61</b>	<b>38.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
<b>(S\$)</b>	8,863.55	4,350.00	4,513.55	50.92
<b>+ GST 7.00/7.00% (S\$)</b>	620.45	304.50	315.95	50.92
<b>Nett Amount (S\$)</b>	<b>9,484.00</b>	<b>4,654.50</b>	<b>4,829.50</b>	<b>50.92</b>

### INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 29/07/2019 Inspected At:

V-Tech Auto Service (HQ)

No.1 Soon Lee Street, #06-04 Pioneer Center  
Singapore 627605

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Mar 2021)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ2817X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Damaged	1,673.50 FL	*1,673.50 FL
2	2		*REAR TAILGATE DAMPERS	Intact	508.40 FL	*- FL
3	2		*REAR TAILGATE HINGES	Intact	137.10 FL	*- FL
4	1		*REAR TAILGATE LOCK	Damaged	223.30 FL	*223.30 FL
5	1		*REAR TAILGATE LOCK STRIKER	Serviceable	48.50 FL	*- FL
6	1		*REAR TAILGATE LOGO	Necessary	61.90 FL	*61.90 FL
7	1		*REAR TAILGATE OUTER GARNISH	Intact	219.20 FL	*- FL
8	1		*REAR TAILGATE RUBBER	Necessary	328.48 FL	*289.00 FL
9	1		*REAR TAILGATE TOYOTA STICKER	Necessary	39.02 FL	*39.02 FL
10	1		*REAR TAILGATE HIACE STICKER	Necessary	39.02 FL	*39.02 FL
11	2		*REAR TAILLAMP	Damaged	493.00 FL	*493.00 FL
12	2		*REAR TAILLAMP PANELS	Repair	923.80 FL	*- FL
13	1		*REAR END PANEL	Damaged	887.90 FL	*887.90 FL
14	1		*REAR END PANEL TOP MOULDING	Intact	99.20 FL	*- FL
15	1		*REAR BUMPER	Damaged	411.95 FL	*411.95 FL
16	4		*REAR BUMPER BRACKETS	Damaged	75.20 FL	*75.20 FL
17	2		*REAR BUMPER SIDE RETAINERS	Serviceable	47.80 FL	*- FL
18	1		*REAR SPARE TYRE CARRIER	Damaged	331.20 FL	*331.20 FL
19	1		*REAR SPARE TYRE CARRIER LOCK CATCH	Damaged	89.60 FL	*89.60 FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
21	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
22	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
23	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,563.07</b>	<b>4,864.59</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,659.52	1,153.65
<b>Total Parts (\$)</b>	<b>5,903.55</b>	<b>3,710.94</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	40.00	40.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	120.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	120.00	60.00
4	TO REMOVE AND REFIT REAR CAMERA	New	150.00	40.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,100.00	650.00
7	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,100.00	700.00
8	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,960.00</b>	<b>1,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >