

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21003086/Gtf3e2	
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date:	22/03/2021	
	ATTN: TAN WAN (	CONG		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKT 2878K	Veh. Inspected		SMK 6892R	
	Policy No.	GA542566/1	Coverage (\$)		0.00	
	Claim No.	S1M034PH	Excess (\$)		0.00	
	Assign From	TAN WAN CONG	Assign Date		09/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO 1.6	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KNAF3416MK5036735	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	NEXEN		6 mm	
	L/H Front Tyre	205/55 R16	NEXEN		6 mm	
	R/H Rear Tyre	205/55 R16	NEXEN		6 mm	
	L/H Rear Tyre	205/55 R16	NEXEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS UNDERCARRIAGE					
5. General Information						
	Accident Date	05/03/2021	Inspect Date /	Time	10/03/2021 ( 12:00 PM )	
	Survey held at	MJE MOTOR				
	BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/ASM21003086/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**