



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2203662

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 14/06/2022
Reference CC4/LPC21003089/Gea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 4041P
Insured Veh. YP 5887U
Claim No. 20/21/21/VC05/024305
Policy No. Z20VC05005600
Accident Date 05/03/2021
Inspection Date 09/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21003089/Gea3q2 Date: 14/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 5887U	Veh. Inspected	SHD 4041P	
Policy No.	Z20VC05005600	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024305	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	09/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40 1.7	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHLB41UMHU098882	Colour	BLUE	
Odometer	368354 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2021	Inspection Date	09/03/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4041P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL ASSY-TRUNK LID	BUCKLED	2,174.90	2,174.90
1	EMBLEM-CRDI	NECESSARY	52.40	52.40
1	EMBLEM-I40	NECESSARY	67.90	67.90
1	SYMBOL MARK-TRUNK LID	NECESSARY	63.10	63.10
1	LAMP ASSY-RR COMB I/S LH	SCRATCHED	1,131.20	1,131.20
1	LAMP ASSY-RR COMB I/S RH	CRACKED	1,131.20	1,131.20
1	COVER ASSY-RR BUMPER	TO REPAIR SEE LABOUR	1,106.00	-
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	COVER-RR BUMPER LWR	NOT NECESSARY	228.00	-
	LESS 20% DISCOUNT		-1,195.34	-928.54
			4,781.36	3,714.16
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT LOGO CTPL (SN)	NECESSARY	30.00	30.00
1	REAR BOOT TEL NUMBER CTPL (SN)	NECESSARY	30.00	30.00
1	PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR ASSY (SN)	NOT NECESSARY	135.70	-
			245.70	110.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF COVER ASSY-RR BUMPER.		600.00	420.00
	SPRAYPAINT ON AFFECTED AREA.		550.00	500.00
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	40.00
			1,280.00	990.00
	GRAND TOTAL		6,307.06	4,814.16



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,850.00
---	--	--	-----------------

Report Ref No. CC4/LPC21003089/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4041P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 4041P

RE-INSPECTION

