

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|-----------------|----------|------------------------|--|
| | AXA INSURANCE I | PTE LTD | F | Ref: | CC4/ASM21003092/Upa3q2 | |
| | 8 SHENTON WAY AXA TOWERSING | | [| Date: | 28/04/2021 | |
| | ATTN:RICHARD A | NG | (| Code: | ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SHA 1303U | Veh. Inspected | | SJS 285B | |
| | Policy No. | VFX/P2419138 | Coverage (\$) | | 0.00 | |
| | Claim No. | S1M034QY | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 09/03/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA VELLFIRE (A) | c.c | | 2362 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2009 | |
| | Chassis No. | ANH208007817 | Colour | | BLACK | |
| | Odometer | 172666 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 235/50 R18 | MICHELIN | | 6 mm | |
| | L/H Front Tyre | 235/50 R18 | MICHELIN | | 6 mm | |
| | R/H Rear Tyre | 235/50 R18 | MICHELIN | | 6 mm | |
| | L/H Rear Tyre | 235/50 R18 | MICHELIN | | 6 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 08/03/2021 | Inspection Date | <u>;</u> | 09/03/2021 | |
| | Survey held at | FASTECH AUTO PTE LTD | | | | |
| | | 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days | | | | | |
| | | | | | | |