

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD AUDI Q5 (SJW74Y)
Date of Loss	4 March 2021
Time of Loss	19:00
Loss Description	SKS7673G (INSD) C/W REAR OF SJW74Y (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$56,614.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJW74Y

Registration State

SINGAPORE

Mileage

104191

Purchase Date

DD/MM/YYYY



Registration Date *

31/07/2014



Age of Vehicle

6

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2014

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION





Driver Name

THIERRY PAUL
HENRI FORICHON

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD AUDI	<input type="text" value="AUDI"/>
Model	Q5	<input type="text" value="Q5 2.0 TFSI QUATTRO "/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="WAUZZZ8R1EA075437"/>
Engine No		<input type="text" value="CNC037457"/>
Engine Capacity		<input type="text" value="1984"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	TBC, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

15/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

235/55R19

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Spare wheel

Rear Tyre Size

235/55R19

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

5

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio













Parts & Labour












Miscellaneous









Summary

Parts

Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE	Repair	0	0	No	0	0	0	0	0
	0	1		TAILGATE LOGO	Necessary	0	85	No	0	5	0	0	80.75
	0	1		TAILGATE EMBLEM 2.0T	Necessary	0	45	No	0	5	0	0	42.75
	0	1		TAILGATE EMBLEM Q5	Necessary	0	55	No	0	5	0	0	52.25
	0	1		TAILGATE RUBBER BEADING	Cut	0	196	No	0	5	0	0	186.2
	0	1		TAILGATE INNER TRIM BOARD	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE GLASS WITH MOULDING	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAIL LAMP LH	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILLAMP INNER COVER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER	Cracked	0	1132.7	No	0	5	0	0	1076.07
	0	1		REAR BUMPER LOWER	Deformed	0	388	No	0	5	0	0	368.6
	0	1		REAR BUMPER REFLECTOR LH	Cracked	0	178.2	No	0	5	0	0	169.29
	0	1		REAR BUMPER REFLECTOR RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER INNER SPONGE	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER INNER PLASTIS	Broken	0	175	No	0	5	0	0	166.25
	0	1		REAR BUMPER BRACKET LH	Bent	0	48	No	0	5	0	0	45.6
	0	1		REAR BUMPER BRACKET RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER RETAINER LH	Broken	0	75	No	0	5	0	0	71.25
	0	1		REAR BUMPER RETAINER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER TOWING COVER	Missing	0	45	No	0	5	0	0	42.75

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER LOWER COVER CENTRE	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER REINFORCEMENT	Bent	0	505.6	No	0	5	0	0	480.32
	0	1		REAR END PANEL	Buckled	0	520	No	0	5	0	0	494
	0	1		REAR END PANEL INNER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL INNER CROSSMEMBER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR END INNER CHROME PANEL	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR END INNER GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	1		EXHAUST PIPE CENTRE	Bent	0	977	No	0	5	0	0	928.15
	0	1		EXHAUST PIPE MOUNTINGS	Serviceable	0	0	No	0	0	0	0	0
	0	1		EXHAUST PIPE CHROME	Bent	0	80	No	0	5	0	0	76
	0	1		EXHAUST MUFFLER	Bent	0	985	No	0	5	0	0	935.75

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		EXHAUST HEAT SHIELD	Serviceable	0	0	No	0	0	0	0	0
	0	1		KEYLESS SENSOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER LH	Buckled	0	350	No	0	5	0	0	332.5
	0	1		REAR FENDER INNER SHIELD LH	Damaged	0	225	No	0	5	0	0	213.75
	0	1		REAR AIR VENT LH	Cut	0	60	No	0	5	0	0	57
	0	1		REAR FENDER INNER SIDE PANEL LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER SIDE TRIM LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR 1/4 GLASS WITH MOULDING	Serviceable	0	0	No	0	0	0	0	0



Labour





















Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRENGTHEN & PANEL BEAT ACCIDENT AREA	0	900	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		SPRAY PAINTING ON AFFECTED AREA	0	800	0	0	Reviewing		
	0		R&R TAILGATE COMPONENTS	0	60	0	0	Reviewing		
	0		R&R AND RESET REVERSE SENSOR	0	40	0	0	Reviewing		
	0		R&R EXHAUST PIPE SYSTEM	0	60	0	0	Reviewing		
	0		R&R INNER TRIM & CARPET TO REPAIR	0	60	0	0	Reviewing		
	0		RESPRAY KOTO TUFF ON ACCIDENT AREA	0	60	0	0	Reviewing		
	0		CHECK WIRING SYSTEM	0	30	0	0	Reviewing		
	0		R&R REAR TAILGATE GLASS	0	0	0	0	Deny		
	0		R&R REAR 1/4 GLASS	0	0	0	0	Deny		
	0		R&R CARPET, SEATS & TRIM TO ASSIST REPAIR	0	0	0	0	Deny		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition











Taxes & Ratio









Parts & Labour







Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 7 DAYS	Reviewing	0	0		
	0	TAILGATE TRIM BOARD CLIPS	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REVERSE SENSOR (4PCS)	Reviewing	0	300	DAMAGED (2PCS ONLY)	
	0	REAR FENDER INNER TRIM CLIPS	Deny	0	0	NOT NECESSARY	
	0	REAR FENDER INNER SHIELD CLIPS	Reviewing	0	30	NECESSARY	
	0	REAR BUMPER CLIPS	Reviewing	0	30	NECESSARY	
	0	REAR NO PLATE	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR TAILGATE GLASS SEALANT	Deny	0	0	NOT NECESSARY	
	0	REAR TAILGATE GLASS INNER SEAL	Deny	0	0	NOT NECESSARY	
	0	REAR TAILGATE GLASS CLEANER & PRIMER	Deny	0	0	NOT NECESSARY	
	0	1/4 GLASS SEALANT	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	1/4 GLASS INNER SEAL	Deny	0	0	NOT NECESSARY	
	0	1/4 GLASS CLEANER & PRIMER	Deny	0	0	NOT NECESSARY	
	0	REAR BUMPER WIRING HARNESS FAN SENSOR	Reviewing	0	120	DAMAGED	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$8,309.23
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$5,819.23
Labour	\$0.00	\$2,010.00
Miscellaneous	\$0.00	\$480.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

6650





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$6,650.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$6,650.00

Submit for Review