



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Hyundai Avante (SJV3555L)
Date of Loss	5 March 2021
Time of Loss	17:45
Loss Description	SGX722R (INS) >> SJV3555L (TP) >> SLB557H
Comment	<input type="text"/>

Workshop Details

Total Rebate
Amount

0

Nett Loss Amount

-\$11,161.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *

20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJV3555L

Registration State

SINGAPORE

Mileage

231387

Purchase Date

DD/MM/YYYY



Registration Date *

22/01/2010



Age of Vehicle

11

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2009

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

LOW KENG ANN
ERIC

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Hyundai	<input type="text" value="HYUNDAI"/>
Model	Avante	<input type="text" value="AVANTE 1.6 AT ABS D/A"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="KMH DU41BMAU93289"/>
Engine No		<input type="text" value="G4FC9U775287"/>
Engine Capacity		<input type="text" value="1591"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	20 August 1980	<input type="text" value="DD/MM/YYYY"/> 
Age	40	
Occupation	Driver	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	TBC, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	S8025442C	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

195/65R15

Front left side

SUMITOMO7mm

Front right side

SUMITOMO7mm

Spare wheel

Rear Tyre Size

195/65R15

Rear left side

SUMITOMO7mm

Rear right side

SUMITOMO7mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

20

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio













Parts & Labour













Miscellaneous













Summary












Parts



Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT BUMPER	Buckled	0	452	No	0	20	0	0	361.6
	0	1		FRONT BUMPER REINFORCEMENT	Bent	0	255	No	0	20	0	0	204
	0	1		FRONT BUMPER SIDE RETAINER RH	Damaged	0	42	No	0	20	0	0	33.6
	0	1		FRONT BUMPER SIDE RETAINER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER BRACKET RH	Repair	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER BRACKET LH	Repair	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER LOWER GRILLE	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT FENDER INNER SHIELD RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		HEADLAMP LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		HEADLAMP RH	Cut	0	489.5	No	0	20	0	0	391.6
	0	1		FRONT SUPPORT PANEL	Cracked	0	753	No	0	20	0	0	602.4
	0	1		FRONT SUPPORT PANEL GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	1		RADIATOR GRILLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		RADIATOR GRILLE LOGO	Serviceable	0	0	No	0	0	0	0	0
	0	1		BONNET	Repair	0	0	No	0	0	0	0	0
	0	1		BONNET HINGE LH	Repair	0	0	No	0	0	0	0	0
	0	1		BONNET HINGE RH	Repair	0	0	No	0	0	0	0	0
	0	1		BONNET LOCK	Repair	0	0	No	0	0	0	0	0
	0	1		BONNET INSULATOR	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		AIRCON CONDENSOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID	Repair	0	0	No	0	0	0	0	0
	0	1		BOOTLID EMBLEM AVANTE	Necessary	0	28.5	No	0	20	0	0	22.8
	0	1		BOOTLID OUTER GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID LAMP LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID LAMP RH	Damaged	0	168	No	0	20	0	0	134.4
	0	1		BOOTLID INNER LOCK	Repair	0	0	No	0	0	0	0	0
	0	1		BOOTLID CATCH	Repair	0	0	No	0	0	0	0	0
	0	1		BOOTLID CABLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID RUBBER	Serviceable	0	0	No	0	0	0	0	0
	0	1		BOOTLID HINGE LH	Repair	0	0	No	0	0	0	0	0
	0	1		BOOTLID HINGE RH	Repair	0	0	No	0	0	0	0	0















EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		BOOTLID INNER TRIM	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP RH	Cut	0	266.5	No	0	20	0	0	213.2
	0	1		TAILLAMP PANEL LH	Repair	0	0	No	0	0	0	0	0
	0	1		TAILLAMP PANEL RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER	Bent	0	442	No	0	20	0	0	353.6
	0	1		REAR BUMPER INNER SPONGE	Cracked	0	122	No	0	20	0	0	97.6
	0	1		REAR BUMPER REINFORCEMENT	Bent	0	215	No	0	20	0	0	172
	0	1		REAR BUMPER REINFORCEMENT STAY	Damaged	0	134.8	No	0	20	0	0	107.84
	0	4		REAR SUPPORT BRACKET	Cracked	0	28.5	No	0	20	0	0	91.2
	0	1		REAR BUMPER RETAINER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER RETAINER RH	Damaged	0	42.5	No	0	20	0	0	34









EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR END PANEL	Repair	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL INNER GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR SPARE TYRE BOARD	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR SPARE TYRE	Repair	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER TRIM RH	Cracked	0	208	No	0	20	0	0	166.4
	0	1		REAR FENDER RH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER SHIELD RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER AIR VENT RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST PIPE	Bent	0	693.8	No	0	20	0	0	555.04
	0	1		REAR EXHAUST PIPE MOUNTING	Serviceable	0	0	No	0	0	0	0	0
	0	1		CENTRE EXHAUST PIPE	Repair	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER SPONGE	Cracked	0	118.6	No	0	20	0	0	94.88

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FOG LAMP RH	Cracked	0	285	No	0	20	0	0	228
	0	1		WASHER TANK	Dented	0	93	No	0	20	0	0	74.4

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRAIGHTEN & PANEL BEAT ACCIDENT AREA - FRONT	0	900	0	0	Reviewing		
	0		STRAIGHTEN & PANEL BEAT ACCIDENT AREA - REAR	0	1000	0	0	Reviewing		
	0		SPRAY PAINTING ON ACCIDENT AREA - FRONT	0	600	0	0	Reviewing		
	0		SPRAY PAINTING ON ACCIDENT AREA - REAR	0	800	0	0	Reviewing		
	0		RESPRAY TUFF KOTE ON ACCIDENT AREA	0	0	0	0	Deny		
	0		R&R REAR WINDSCREEN GLASS	0	0	0	0	Deny		
	0		CHECK & REPAIR WIRING SYSTEM	0	40	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		R&R AIRCON CONDENSOR & TOP UP GAS	0	100	0	0	Reviewing		
	0		R&R BOOTLID COMPARTMENT	0	0	0	0	Deny		
	0		R&R SEATS, CARPET & TRIM TO ASSIST REPAIR	0	60	0	0	Reviewing		
	0		R&R REAR EXHAUST PIPE	0	60	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition









Taxes & Ratio

Parts & Labour



Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 8 DAYS	Reviewing	0	0		
	0	FRONT BUMPER CLIPS	Reviewing	0	50	NECESSARY	
	0	FRONT NO. PLATE	Reviewing	0	45	DENTED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FRONT FENDER INNER SHIELD CLIPS	Deny	0	0	NOT NECESSARY	
	0	BONNET INSULATOR CLIPS	Deny	0	0	NOT NECESSARY	
	0	REAR BUMPER CLIPS	Reviewing	0	50	NECESSARY	
	0	REAR NO. PLATE	Deny	0	0	SERVICEABLE	
	0	REAR END PANEL GARNISH CLIPS	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR FENDER INNER SHIELD CLIPS	Deny	0	0	NOT NECESSARY	
	0	SPARE TYRE SEALANT	Deny	0	0	NOT NECESSARY	
	0	REAR END PANEL SEALANT	Deny	0	0	NOT NECESSARY	
	0	REVERSE SENSOR	Reviewing	0	200	CRACKED	
	0	REAR WINDSCREEN SEALANT	Deny	0	0	NOT NECESSARY	
	0	REAR WINDSCREEN INNER SEAL	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR WINDSCREEN CLEANER & PRIMER	Deny	0	0	NOT NECESSARY	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$7,843.56
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$3,938.56
Labour	\$0.00	\$3,560.00
Miscellaneous	\$0.00	\$345.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

6250





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$6,250.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$6,250.00

Submit for Review