



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 1584G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BROKEN	495.00	495.00
1	REAR BUMPER REFLECTOR LH	BROKEN	45.00	45.00
1	REAR BUMPER LOWER GARNISH	BROKEN	255.00	255.00
1	REAR BUMPER UNDER COVER	NOT NECESSARY	39.00	-
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	30.00
1	REAR BUMPER SIDE RETAINER LH	BROKEN	44.00	44.00
1	REAR BUMPER REINFORCEMENT	BENT	295.00	295.00
1	REAR FENDER COWLING LH	NOT NECESSARY	55.00	-
10	REAR FENDER COWLING CLIPS @\$3.50	NOT NECESSARY	35.00	-
1	REAR FENDER MUDFLAP COVER LH REAR	CUT	29.00	29.00
1	REAR AIR VENT LH	NOT NECESSARY	38.00	-
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-273.00	-238.60
			1,092.00	954.40
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	<u>LABOUR</u>			
	TO INSTALL REVERSE SENSOR & CHECK WIRING.		80.00	30.00
	TO KNOCK & STRAIGHTEN ON END PANEL.TO REMOVE & REPLACE DAMAGED ITEMS,REALIGN CONNECTION.		400.00	300.00
	TO SPRAY PAINT ON REPAIRED AREAS.		400.00	400.00
			880.00	730.00
	GRAND TOTAL		2,252.00	1,884.40

RECOMMENDED COST OF REPAIRS			1,884.40
------------------------------------	--	--	-----------------

Report Ref No. CS/SMO21003103/EKtf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.