



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9315S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | COVER,FRONT BUMPER | BUCKLED | 516.00 | 516.00 |
| 1 | REINFORCEMENT SUB-ASSY,FRONT BUMPER | TO REPAIR SEE LABOUR | 716.60 | - |
| 1 | ABSORBER,FRONT BUMPER ENERGY | SERVICEABLE | 79.60 | - |
| 1 | FRONT BUMPER SIDE RETAINER RH | NECESSARY | 80.10 | 80.10 |
| 1 | BRACKET,FRONT BUMPER SIDE,RH | SERVICEABLE | 59.30 | - |
| 1 | SUPPORT,FRONT BUMPER SIDE,RH | SERVICEABLE | 80.10 | - |
| 1 | LAMP ASSY,FOG,RH | SERVICEABLE | 951.40 | - |
| 1 | UNIT ASSY,HEADLAMP,RH | SERVICEABLE | 2,637.60 | - |
| 1 | COMPUTER SUB-ASSY,HEADLAMP,RH NO.1 | SERVICEABLE | 960.50 | - |
| 1 | LINER,FRONT FENDER,RH | SERVICEABLE | 206.70 | - |
| 1 | FENDER SUB-ASSY,FRONT RH | BENT | 977.80 | 977.80 |
| 1 | EMBLEM,SIDE PANEL,RH | NECESSARY | 54.60 | 54.60 |
| 1 | JAR ASSY,WINDSHIELD WASHER | SERVICEABLE | 219.10 | - |
| | LESS 25% DISCOUNT | | -1,884.85 | -407.12 |
| | | | 5,654.55 | 1,221.38 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | WHEEL RIM (SN) | SERVICEABLE | 1,879.40 | - |
| 1 | TYRE 195/65/15 (SN) | SERVICEABLE | 350.00 | - |
| 1 | RIM COVER (SN) | SERVICEABLE | 400.00 | - |
| 1 | FRONT BUMPER RETAINER CLIP (SN) | NECESSARY | 66.00 | 50.00 |
| 1 | FRONT BUMPER BRACKET CLIP (SN) | NOT NECESSARY | 60.00 | - |
| 1 | SET FRONT BUMPER CLIP (SN) | NOT NECESSARY | 66.00 | - |
| 1 | SET FRONT FENDER CLIP (SN) | NOT NECESSARY | 65.00 | - |
| 1 | SET FRONT FENDER LINER CLIP (SN) | NOT NECESSARY | 75.00 | - |
| | | | 2,961.40 | 50.00 |
| <u>LABOUR</u> | | | | |
| | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY,FRONT BUMPER. | | 1,600.00 | 400.00 |

Report Ref No. CS/AGI21003104/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR. | NOT NECESSARY | 380.00 | - |
| | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS. | | 240.00 | 30.00 |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | - |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 1,600.00 | 440.00 |
| | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING. | NOT NECESSARY | 170.00 | - |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | | 170.00 | 10.00 |
| | | | 4,380.00 | 880.00 |
| GRAND TOTAL | | | 12,995.95 | 2,151.38 |
| RECOMMENDED COST OF REPAIRS | | | | 2,151.38 |

Report Ref No. CS/AGI21003104/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.