

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003112/UGS3Q2
Date: 24/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100468219
Claimant Vehicle No :	FBQ930C	Insured Vehicle No :	SBK103E
Date of Loss:	06/03/2021	Nature of Claim:	TP
		Claim No:	2526616625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ930C		
Make & Model:	YAMAHA NMAX155, 155cc ABS CVT	Engine No:	G3H6E0013235
Reg. Date:	29/07/2019 (Man. Year: 2019)	Chassis No:	MH3SG431000010578
Colour:	White	Odometer:	11960 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110-70 R13	Rear Tyre Size:	130-70 R13
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,571.00	1,382.90	188.10	11.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	504.00	350.00	154.00	30.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,075.00	1,732.90	342.10	16.49
Nett Amount (S\$)	2,220.25	1,854.20	366.05	16.49

+ Loss of Use (3.0 x S\$20.00/day) (S\$)	60.00
+ Doc/Search Fee (S\$)	2.00
Nett Liability (S\$)	1,916.20

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 09/03/2021

Estimated Period of Repair: 3.0 days

Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	35.00 F	*35.00 FL
2	1		*BOARD FOOTREST RH	Cut	55.00 F	*55.00 FL
3	1		*BOX REAR KAPPA K47 MANTA	Cut	300.00 F	*280.00 FL
4	1		*BRACKET BOX REAR (GIVI)	Bent	65.00 F	*65.00 FL
5	1		*COVER SIDE CNETRE RH (WHITE)	Cut	24.00 F	*24.00 FL
6	1		*COWLING FRONT RH (WHITE)	Cut	34.00 F	*34.00 FL
7	2		*EMBLEM (ABS)	Necessary	22.00 F	*22.00 FL
8	1		*EMBLEM (YAMAHA) LOGO	Necessary	16.00 F	*16.00 FL
9	1		*ENGINE BRACKET COMP	Bent	73.00 F	*73.00 FL
10	1		*GASKET EXHAUST PIPE	Necessary	13.00 F	*13.00 FL
11	1		*LAMP TAIL ASSY	Broken	240.00 F	*240.00 FL
12	1		*MIRROR RH	Cut	38.00 F	*38.00 FL
13	1		*MUDGUARD FRONT (WHITE)	Cut	49.00 F	*49.00 FL
14	1		*MUDGUARD REAR	Distorted	54.00 F	*54.00 FL
15	1		*PANEL 2 (MATT BLACK)RH	Scratched	24.00 F	*24.00 FL
16	1		*PIPE EXHAUST ASSY	Dented	423.00 F	*423.00 FL
17	1		*PROTECTOR EXHAUST	Cut	40.00 F	*40.00 FL
18	1		*REFLECTOR ASSY REAR (CENTRE)	Cracked	16.00 F	*16.00 FL
19	2		*REFLECTOR REAR	N/S Missing / O/S Cracked	10.00 F	*10.00 FL
20	5		*RIVET	Necessary	10.00 F	*10.00 FL
21	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	30.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,571.00	1,535.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	152.10
Total Parts (S\$)	1,571.00	1,382.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	504.00	350.00
Gross Labour Cost (S\$)			504.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >