

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003122/GS3Q2
Date: 09/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SDR983X	Insured Vehicle No :	SKK8873G
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	6550920896SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR983X		
Make & Model:	LEXUS IS250C, 2.5 (A)	Engine No:	4GR0771392
Reg. Date:	30/09/2011 (Man. Year: 2011)	Chassis No:	JTHBK262605157315
Colour:	Black	Odometer:	125584 km
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	82,662.64	14,859.90	67,802.74	82.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,550.00	3,420.00	9,130.00	72.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	95,212.64	18,279.90	76,932.74	80.80
Approved Total (Overridden) (S\$)		14,600.00		

(S\$)	95,212.64	14,600.00	80,612.64	84.67
+ GST 7.00/7.00% (S\$)	6,664.88	1,022.00	5,642.88	84.67
Nett Amount (S\$)	101,877.52	15,622.00	86,255.52	84.67
+ Car Rental (12.0 x S\$107.00/day) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		65.45		
Nett Liability (S\$)		16,971.45		

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 09/03/2021

Estimated Period of Repair: 10.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,980.10 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	510.80 FL	*- FL
3	1		*BONNET SEAL	Not Necessary	150.90 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	387.20 FL	*- FL
5	1		*BONNET STRIKER LOCK	Not Necessary	87.50 FL	*- FL
6	2		*BONNET HINGE LH/RH	Not Necessary	396.00 FL	*- FL
7	1		*HEAD LAMP LH/RH	O/SNot Necessary /N/SMtgBroken	5,780.20 FL	*2,188.00 FL
8	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	403.80 FL	*- FL
9	2		*HEAD LAMP ECU LH/RH	Not Necessary	3,379.60 FL	*- FL
10	1		*HEAD LAMP WIRE HARNESS	Not Necessary	1,992.00 FL	*- FL
11	1		*FRONT GRILLE	Not Necessary	682.00 FL	*- FL
12	1		*FRONT GRILLE BASE	Cracked	701.00 FL	*501.50 FL
13	1		*FRONT GRILLE CHROME	Cracked	591.00 FL	*257.90 FL
14	1		*FRONT BUMPER	Distorted	2,001.00 FL	*881.90 FL
15	1		*FRONT BUMPER GRILLE	Not Necessary	482.00 FL	*- FL
16	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	1,020.02 FL	*- FL
17	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	784.20 FL	*- FL
18	2		*FRONT BUMPER FOG LAMP HOLDER LH/RH	Not Necessary	556.80 FL	*- FL
19	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,930.00 FL	*- FL
20	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	78.20 FL	*- FL
21	1		*FRONT BUMPER UNDER COVER	Not Necessary	410.00 FL	*- FL
22	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	390.00 FL	*- FL
23	1		*FRONT BUMPER SPONGE	Torn	423.00 FL	*185.20 FL
24	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,692.00 FL	*- FL
25	2		*FRONT REINFORCEMENT BAR BRACKET LH/RH	Not Necessary	782.40 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Not Necessary	2,180.00 FL	*- FL
27	1		*A/C CONDENSER	Not Necessary	2,009.80 FL	*- FL
28	1		*A/C CONDENSER SUCTION PIPE	Not Necessary	982.40 FL	*- FL
29	1		*A/C CONDENSER DISCHARGE PIPE	Not Necessary	1,004.20 FL	*- FL
30	1		*RADIATOR ASSY	Not Necessary	2,390.80 FL	*- FL
31	1		*RADIATOR FAN MOTOR	Not Necessary	692.38 FL	*- FL
32	1		*RADIATOR FAN BLADE	Not Necessary	398.40 FL	*- FL
33	1		*RADIATOR FAN COWLING	Not Necessary	701.50 FL	*- FL
34	1		*AIR FILTER HOUSING	Not Necessary	872.90 FL	*- FL
35	2		*FRONT FENDER LH/RH	Not Necessary	2,880.58 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	461.80 FL	*- FL
37	1		*BOOTLID	Dented	1,310.00 FL	*1,260.40 FL
38	1		*BOOTLID LOGO	Necessary	295.00 FL	*90.00 FL
39	1		*BOOTLID LEXUS EMBLEM	Necessary	2,450.00 FL	*70.00 FL
40	1		*BOOTLID IS250 EMBLEM	Necessary	2,140.00 FL	*80.00 FL
41	1		*BOOTLID OUTER GARNISH	Cracked	697.80 FL	*513.30 FL
42	1		*BOOTLID LAMP LH/RH	N/S Broken / O/S Not Necessary	1,396.20 FL	*484.30 FL
43	1		*BOOTLID SWITCH	Not Necessary	481.00 FL	*- FL
44	1		*BOOTLID LOCK	Damaged	895.00 FL	*423.40 FL
45	1		*BOOTLID STRIKER LOCK	Bent	590.00 FL	*205.00 FL
46	1		*BOOTLID WEATHERSTRIP	Deformed	610.00 FL	*293.10 FL
47	1		*BOOTLID INNER TRIM	Deformed	711.00 FL	*561.80 FL
48	2		*BOOTLID NO PLATE LAMP LH/RH	Not Necessary	601.00 FL	*- FL
49	2		*BOOTLID HINGE LH/RH	Serviceable	320.00 FL	*- FL
50	1		*TAIL LAMP LH/RH	N/S Broken / O/S Not Necessary	2,194.20 FL	*693.10 FL
51	1		*TAIL LAMP PANEL LH/RH	N/S Dented / O/S Not Necessary	996.40 FL	*385.00 FL
52	1		*TAIL LAMP SIDE GARNISH TOP LH/RH	N/S Deformed	603.80 FL	*111.40 FL
53	1		*TAIL LAMP SIDE GARNISH LOWER LH/RH	N/S Broken / O/S Not Necessary	622.40 FL	*103.10 FL
54	1		*REAR BUMPER	Dented	2,291.40 FL	*854.00 FL
55	1		*REAR BUMPER SIDE RETAINER LH/RH	N/S Bent / O/S Not Necessary	296.00 FL	*75.10 FL
56	1		*REAR BUMPER TOW HOOK COVER	Serviceable	95.00 FL	*- FL
57	1		*REAR BUMPER REFLECTOR LH/RH	N/S Broken / O/S Not Necessary	388.00 FL	*154.00 FL
58	1		*REAR BUMPER SPONGE	Torn	384.00 FL	*107.50 FL
59	1		*REAR BUMPER UNDER COVER	Not Necessary	491.20 FL	*- FL
60	1		*REAR BUMPER CENTER BRACKET	Not Necessary	356.10 FL	*- FL
61	1		*REAR REINFORCEMENT BAR	Dented	1,692.20 FL	*580.00 FL
62	1		*REAR KEYLESS SENSOR	Not Necessary	394.00 FL	*- FL
63	1		*REAR KEYLESS BUZZER	Not Necessary	398.00 FL	*- FL
64	1		*REAR END PANEL	Dented	1,892.40 FL	*830.00 FL
65	1		*REAR END PANEL TOP GARNISH	Broken	425.90 FL	*342.00 FL
66	1		*SPARE WHEEL PANEL	Not Necessary	2,870.00 FL	*- FL
67	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	925.60 FL	*- FL
68	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	1,380.00 FL	*- FL
69	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	405.90 FL	*- FL
70	1		*REAR FENDER LH/RH	N/S Dented / O/S Not Necessary	5,960.00 FL	*1,445.00 FL
71	1		*REAR FENDER INNER TRIM LH/RH	N/S Deformed / O/S Not Necessary	2,028.20 FL	*412.00 FL
72	1		*REAR EXHAUST PIPE	Not Necessary	2,014.50 FL	*- FL
73	1		*REAR EXHAUST MUFFLER	Bent / Dented	980.50 FL	*980.50 FL
74	1		*REAR EXHAUST MOUNTING	Not Necessary	210.00 FL	*- FL
75	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	2,298.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*REAR WINDSCREEN MOULDING	Necessary	430.20 FL	*122.50 FL
77	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	1,280.00 FL	*640.00 FL
78	1		*REAR BUMPER SENSOR HARNESS	Broken	480.00 FL	*480.00 FL
79	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
80	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
81	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
82	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
83	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
84	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
85	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
86	1		*FRONT BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
87	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
88	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
89	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
90	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
91	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*20.00 FS
92	1		*REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*15.00 FS
93	1		*BOOTLID INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
94	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
95	1		*REAR BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
96	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
97	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
98	1		*REAR WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
99	1		*COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	91,707.38	16,491.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	9,044.74	1,631.10
Total Parts (\$\$)	82,662.64	14,859.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,400.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,400.00	300.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,600.00	1,200.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,600.00	900.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
8	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	400.00	0.00
9	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	120.00
10	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
11	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	150.00	60.00
12	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
13	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			12,550.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >