

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21003123/AGS3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SMR1953U	Insured Vehicle No :	GBF5815C
Date of Loss:	07/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001050

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1953U		
Make & Model:	BMW 216I, 1.5 GRAN TOURER (A)	Engine No:	40765823B38A15A
Reg. Date:	23/12/2019 (Man. Year: 2019)	Chassis No:	WBA6V120705P29871
Colour:	Black	Odometer:	5018 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,696.55	12,646.12	5,050.43	28.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	3,380.00	3,000.00	47.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,076.55	16,026.12	8,050.43	33.44
Approved Total (Overridden) (S\$)		12,305.00		

Nett Amount (S\$)	24,076.55	12,305.00	11,771.55	48.89
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,012.45		
Global Sum Settlement (S\$)		13,000.00		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 08/03/2021

Estimated Period of Repair: 10.0 days

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2021)
Parts:	M1-MPV	BMW 216I 1.5 GRAN TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR1953U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,058.80 F	*1,058.80 FL
2	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
3	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
4	1		*FRONT BUMPER INNER FOAM WITH GARNISH	Cracked	135.00 F	*135.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	530.00 F	*530.00 FL
6	1		*FRONT BUMPER LOWER REINFORCEMENT	Not Necessary	420.00 F	*- FL
7	2		*FRONT BUMPER INNER SIDE RETAINER	Cracked	170.00 F	*170.00 FL
8	1		*FRONT BUMPER LOWER CENTER GARNISH	Cracked	120.00 F	*120.00 FL
9	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	210.00 F	*- FL
10	2		*FRONT BUMPER SIDE OUTER GARNISH	Not Necessary	220.00 F	*- FL
11	1		*FRONT SUPPORT PANEL	Not Necessary	650.00 F	*- FL
12	1		*FRONT SUPPORT AIR DUCT	Cracked	585.00 F	*585.00 FL
13	2		*FRONT GRILLE	Not Necessary	285.30 F	*- FL
14	2		*FRONT GRILLE CHROME	Cut	220.40 F	*220.40 FL
15	6		*FRONT GRILLE CLIP	Necessary	39.00 F	*39.00 FL
16	2		*FRONT HEAD LAMP	Cracked	2,112.40 F	*2,112.40 FL
17	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	270.00 F	*- FL
18	2		*REAR BOOT LID HINGE	Not Necessary	190.00 F	*- FL
19	1		*REAR BOOT LID	Dented	1,216.40 F	*1,216.40 FL
20	1		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	225.00 F	*- FL
21	1		*REAR BOOT LID EMBLEM LOGO	Necessary	95.00 F	*95.00 FL
22	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
23	1		*REAR BOOT LID LOCK	Damaged	212.00 F	*212.00 FL
24	1		*REAR BOOT LID RUBBER	Cut	125.00 F	*125.00 FL
25	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	284.05 F	*284.05 FL
26	12		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	78.00 F	*30.00 FL
27	2		*REAR BOOT LID SIDE REFLECTOR	Cut	716.00 F	*716.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*REAR TAIL LAMP	Cut	557.50 F	*557.50 FL
29	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	156.00 F	*- FL
30	1		*REAR BUMPER	Distorted	1,050.65 F	*1,050.65 FL
31	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
32	2		*REAR BUMPER SIDE RETAINER	Cracked	284.00 F	*284.00 FL
33	2		*REAR BUMPER CENTER RETAINER	Cracked	244.00 F	*244.00 FL
34	2		*REAR BUMPER SIDE REFLECTOR	Cracked	110.00 F	*110.00 FL
35	1		*REAR BUMPER REINFORCEMENT	Bent	728.00 F	*728.00 FL
36	1		*REAR BUMPER TOWING COVER	Not Necessary	61.00 F	*- FL
37	4		*REAR BUMPER REVERSE SENSOR	Damaged (3 PCS ONLY)	1,312.00 F	*984.00 FL
38	4		*REAR BUMPER REVERSE SENSOR HOLDER BRACKET	Not Necessary	292.00 F	*- FL
39	4		*REAR BUMPER REVERSE SENSOR SEAL RUBBER	Necessary	60.00 F	*60.00 FL
40	1		*REAR END PANEL	Dented	917.00 F	*917.00 FL
41	1		*REAR END PANEL TOP GARNISH	Cracked	182.00 F	*182.00 FL
42	1		*REAR EXHAUST	Bent	1,015.05 F	*1,015.05 FL
43	2		*REAR EXHAUST MOUNTING	Not Necessary	170.00 F	*- FL
44	1		*REAR EXHAUST ALUMINIUM COVER	Crumpled	160.00 F	*160.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	17,696.55	14,051.25
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,405.13
Total Parts (S\$)	17,696.55	12,646.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	160.00
2	TO REMOVE & REFIT REAR EXHAUST	New	380.00	100.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
4	GUM	New	50.00	50.00
5	TO REMOVE & REFIT REAR SENSOR	New	120.00	60.00
6	TO CHECK WIRING	New	80.00	60.00
7	TUFF KOTE	New	150.00	80.00
8	PANEL BEATING	New	2,800.00	1,500.00
9	SPRAY PAINTING	New	2,400.00	1,250.00
Gross Labour Cost (\$\$)			6,380.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >