



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

08/03/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111
Ceiling.

+

Accident date: 07/03/2021

Estimated repair cost for vehicle no: SMR1953U BMW 216I GRAN TOURER 19'

CHASSIS: WBA6V120705P29871

S/n	Qty	Items	U/price	Amount	
1	1	Front Bumper <i>Deformed</i>		\$1,058.80	✓
2	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00	30 ✓
3	1	Front Bumper Number Plate <i>Bent</i>		\$50.00	✓
4	1	Front Bumper Inner Foam with garnish <i>crushed</i>		\$135.00	✓
6	1	Front Bumper Reinforcement <i>Bent</i>		\$530.00	✓
7	1	Front Bumper Lower Reinforcement <i>New</i>		\$420.00	x
8	2	Front Bumper Inner Side Retainer <i>crushed</i>	\$85.00	\$170.00	✓
9	1	Front Bumper Lower Center Garnish <i>crushed</i>		\$120.00	✓
10	2	Front Bumper Fog Lamp Garnish <i>new</i>	\$105.00	\$210.00	x
11	2	Front Bumper Side Outer Garnish <i>new</i>	\$110.00	\$220.00	x
12	1	Front Support Panel <i>new</i>		\$650.00	x
13	1	Front Support Air Duct <i>crushed</i>		\$585.00	✓
14	2	Front Grille <i>new</i>	\$142.65	\$285.30	x
15	2	Front Grille Chrome <i>new</i>	\$110.20	\$220.40	✓
16	6	Front Grille Clip <i>new</i>	\$6.50	\$39.00	✓
17	2	Front Head Lamp <i>crushed</i>	\$1,056.20	\$2,112.40	✓
18	2	Front Head Lamp Lower Bracket <i>new</i>	\$135.00	\$270.00	x
19	1	Rear Boot Lid <i>dented</i>		\$1,216.40	✓
20	2	Rear Boot Lid Hinge <i>new</i>	\$95.00	\$190.00	+
21	1	Rear Boot Lid Shock Absorber <i>new</i>		\$225.00	+
22	1	Rear Boot Lid Emblem Logo <i>new</i>		\$95.00	✓
23	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	+
24	1	Rear Boot Lid Lock <i>dented</i>		\$212.00	✓
25	1	Rear Boot Lid Rubber <i>new</i>		\$125.00	✓
26	1	Rear Boot Lid Inner Trim Board <i>crushed</i>		\$284.05	✓
27	12	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$78.00	30 ✓
28	2	Rear Boot Lid Side Reflector <i>new</i>	\$358.00	\$716.00	✓
29	2	Rear Tail Lamp <i>new</i>	\$278.75	\$557.50	✓

30	2	Rear Tail Lamp Lower Bracket	Not new	\$78.00	\$156.00	+
31	1	Rear Bumper	Dislodged		\$1,050.65	-
32	10	Rear Bumper Clip	new	\$6.50	\$65.00	30
33	2	Rear Bumper Side Retainer	crushed	\$142.00	\$284.00	-
34	2	Rear Bumper Center Retainer	crushed	\$122.00	\$244.00	-
35	2	Rear Bumper Side Reflector	crushed	\$55.00	\$110.00	-
36	1	Rear Bumper Reinforcement	Bent		\$728.00	-
37	1	Rear Bumper Towing Cover	Not new		\$61.00	+
38	4	Rear Bumper Reverse Sensor	2 pieces damaged	\$328.00	\$1,312.00	384
39	4	Rear Bumper Reverse Sensor Holder Bracket	new	\$73.00	\$292.00	+
40	4	Rear Bumper Reverse Sensor Seal Rubber	new	\$15.00	\$60.00	-
41	1	Rear End Panel	Dented		\$917.00	-
42	1	Rear End Panel Top Garnish	crushed		\$182.00	-
43	1	Rear Exhaust	Bent		\$1,015.05	✓
44	2	Rear Exhaust Mounting	Not new	\$85.00	\$170.00	+
45	1	Rear Exhaust Aluminium Cover	crushed		\$160.00	✓

Subtotal :- \$17,696.55

Labour charges

To remove & refit cushion & trim board	\$280.00	160
To remove & refit rear exhaust	\$380.00	100
To remove & refit rear windscreen	\$120.00	-
Gum	\$50.00	-
To remove & refit rear sensor	\$120.00	80
To check wiring	\$80.00	60
Tuff kote	\$150.00	80
Panel beating	\$2,800.00	1500
Spray painting	\$2,400.00	1250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$6,380.00

Total:- \$24,076.55

12.8k