

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21003129/EQD3E2

**Date:** 12/04/2021

### REFERENCE

Insured/Claimant: HOE KAH HUI Policy No: 1900084992  
Date of Loss: 08/03/2021 Nature of Claim: OD Claim No: 0945271040SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK4145C**  
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11AC1361  
Reg. Date: 09/04/2019 (Man. Year: 2018) Chassis No: GF7W0600580  
Colour: Red Odometer: 28596 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$99,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Toyo 4 mm Rear Left Side: Toyo 4 mm  
Front Right Side: Toyo 4 mm Rear Right Side: Toyo 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,438.03	2,773.52	664.51	19.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	2,330.00	2,030.00	46.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,798.03</b>	<b>5,103.52</b>	<b>2,694.51</b>	<b>34.55</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>7,198.03</b>	<b>4,503.52</b>	<b>2,694.51</b>	<b>37.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>503.86</b>	<b>315.25</b>	<b>188.61</b>	<b>37.43</b>
<b>Nett Amount (S\$)</b>	<b>7,701.89</b>	<b>4,818.77</b>	<b>2,883.12</b>	<b>37.43</b>

### INSPECTION

Date of Assignment: 09/03/2021  
Date Inspected: 09/03/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, RR BUMPER	Dented	811.00 FL	*811.00 FL
3	1		*BRKT, R/BMPR FACE SIDE, RH	Not Necessary	12.00 FL	*- FL
4	1		*REINFORCEMENT, RR BUMPER, RH	Not Necessary	79.00 FL	*- FL
5	8		*CLIP, ENG ROOM COVER	Not Necessary	16.00 FL	*- FL
6	1		*EXTENSION, RR BUMPER	Cut	292.00 FL	*292.00 FL
7	1		*MOULDING, RR BUMPER, RH	Necessary	106.00 FL	*106.00 FL
8	1		*MOULDING, RR WHEEL ARCH, RH	Not Necessary	160.00 FL	*- FL
9	1		*LAMP ASSY, COMB, RR RH	Broken	603.00 FL	*603.00 FL
10	1		*LAMP ASSY, TAIL, RH	Broken	506.00 FL	*506.00 FL
11	1		*REFLECTOR, TAIL LAMP, RH	Not Necessary	100.00 FL	*- FL
12	1		*PANEL ASSY, TAILGATE	Dented	989.00 FL	*989.00 FL
13	1		*GARNISH, TAILGATE	Not Necessary	496.00 FL	*- FL
14	2		*DAM, TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
15	4		*FASTENER, WINDSHIELD	Necessary	24.00 FL	*24.00 FL
16	1		*DAM, TAILGATE, UPR	Necessary	13.00 FL	*13.00 FL
17	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
18	1		*DAM, TAILGATE, LWR	Necessary	41.00 FL	*41.00 FL
19	1		*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL
20	1		*DECAL, MIVEC	Necessary	36.00 FL	*36.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,459.00</b>	<b>3,596.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b>	1,020.97	822.48
<b>Total Parts (\$\$)</b>	<b>3,438.03</b>	<b>2,773.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW TAILGATE & RR BUMPER. REPAIR RR END PNL & RHR FENDER	New	1,800.00	900.00
2	RESPRAY RR BUMPER, TAILGATE, RR END PNL & RHR FENDER	New	1,400.00	700.00
3	REMOVE & REFIT TAILGATE COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REMOVE & REFIT RR WINDSCREEN GLASS	New	280.00	280.00
8	SUPPLY RR WINDSCREEN SEALANT	New	80.00	80.00
9	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
10	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
11	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	0.00
12	SUPPLY C&C BADGE	New	40.00	40.00
13	SUPPLY REVERSE SENSOR	New	220.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >