



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table border="0"> <tr> <td>Cust No/Name</td> <td>KCV10970/MR Hoe Kah Hui (he Jiahui)</td> </tr> <tr> <td>Reg No/Reg Date</td> <td>SMK4145C / 09/04/201</td> </tr> <tr> <td>Date In/Mileage</td> <td>/ 0</td> </tr> <tr> <td>Chassis No</td> <td>GF7W0600580</td> </tr> <tr> <td>Engine No</td> <td>4J11AC1361</td> </tr> <tr> <td>Make/Model</td> <td>MIT/19MY OUTLANDER 2.0 MODERN(995)</td> </tr> <tr> <td>Colour/Trim</td> <td>P02 RED METALLIC / BK BLACK</td> </tr> </table>	Cust No/Name	KCV10970/MR Hoe Kah Hui (he Jiahui)	Reg No/Reg Date	SMK4145C / 09/04/201	Date In/Mileage	/ 0	Chassis No	GF7W0600580	Engine No	4J11AC1361	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)	Colour/Trim	P02 RED METALLIC / BK BLACK
Cust No/Name	KCV10970/MR Hoe Kah Hui (he Jiahui)														
Reg No/Reg Date	SMK4145C / 09/04/201														
Date In/Mileage	/ 0														
Chassis No	GF7W0600580														
Engine No	4J11AC1361														
Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)														
Colour/Trim	P02 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/03/2021/ 17:02	BLE	261 / Edwin Caina	63746

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW TAILGATE & RR BUMPER REPAIR RR END PNL & RHR FENDER	2 X 450			900 1800.00
E PNT98000 RESPRAY RR BUMPER, TAILGATE, RR END PNL & RHR FENDER	2 X 350			700 1400.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT				120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET				120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS				280.00
M SUNDRY SUPPLY RR WINDSCREEN SEALANT				80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				50.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				60.00
M SUNDRY SUPPLY REVERSE SENSOR				220.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY SUPPLY C&C BADGE				40.00
M SUNDRY Sundries				20.00
M FACE, RR BUMPER	1.00	811.00	23.00	624.47
M BRKT, R/BMPR FACE SIDE, RH	1.00	12.00	23.00	9.24
M REINFORCEMENT, RR BUMPER, RH	1.00	79.00	23.00	60.83

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV10970/MR Hoe Kah Hui (he Jiahui)
	Reg No/Reg Date	SMK4145C / 09/04/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600580
	Engine No	4J11AC1361
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/03/2021/ 17:02	BLE	261 / Edwin Caina	63746

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CLIP, ENG ROOM COVER <i>x NM cut (silver)</i>	8.00	2.00	23.00	12.32
M EXTENSION, RR BUMPER	1.00	292.00	23.00	224.84
M MOULDING, RR BUMPER, RH <i>RPC</i>	1.00	106.00	23.00	81.62
M MOULDING, RR WHEEL ARCH, RH <i>x NM</i>	1.00	160.00	23.00	123.20
M LAMP ASSY, COMB, RR RH <i>BR</i>	1.00	603.00	23.00	464.31
M LAMP ASSY, TAIL, RH <i>BR</i>	1.00	506.00	23.00	389.62
M REFLECTOR, TAIL LAMP, RH <i>x NM</i>	1.00	100.00	23.00	77.00
M PANEL ASSY, TAILGATE <i>DO</i>	1.00	989.00	23.00	761.53
M GARNISH, TAILGATE <i>x NM</i>	1.00	496.00	23.00	381.92
P DAM, TAILGATE SIDE <i>RPC</i>	2.00	27.00	23.00	41.58
M FASTENER, WINDSHIELD <i>RPC</i>	4.00	6.00	23.00	18.48
M DAM, TAILGATE, UPR <i>RPC</i>	1.00	13.00	23.00	10.01
M STOPPER, WINDSHIELD GLASS <i>RPC</i>	2.00	3.00	23.00	4.62
M DAM, TAILGATE, LWR <i>RPC</i>	4.00	41.00	23.00	31.57
M MARK, OUTLANDER <i>RPC</i>	1.00	95.00	23.00	73.15
M DECAL, MIVEC <i>RPC</i>	1.00	36.00	23.00	27.72

Estimate

SURVEYOR NAME: Steve CLKK) 9/3/21, 3.09pm
 SURVEYOR SIGNATURE: OD-NM AL
 DATE: EX-100-?
 REMARKS: PIP, Ry BL SJ
5 days

Confirm & accepted by	Nett	7,798.03
	7% GST on	545.86
	Total Payable	8,343.89

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.