

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21003130/AGS3Q2  
**Date:** 17/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
<b>Claimant Vehicle No :</b>	SLK683D	<b>Insured Vehicle No :</b>	GBK7339X
Date of Loss:	05/03/2021	Nature of Claim:	TP
		Claim No:	7772077374SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLK683D</b>	Engine No:	G4FGGU275637
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU310789
Reg. Date:	04/01/2017 (Man. Year: 2016)	Odometer:	392886 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,607.20	2,048.00	2,559.20	55.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,500.00	1,300.00	46.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,407.20</b>	<b>3,548.00</b>	<b>3,859.20</b>	<b>52.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		

<b>Nett Amount (S\$)</b>	<b>7,407.20</b>	<b>2,800.00</b>	<b>4,607.20</b>	<b>62.20</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>Nett Liability (S\$)</b>		<b>3,160.00</b>		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 08/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Leang Automotive (Kaki Bukit)  
 AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68  
 Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 F	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Necessary	88.60 F	*88.60 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	250.30 F	*250.30 FL
5	1		*REAR BUMPER REFLECTOR	O/S Cracked	191.20 F	*95.60 FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	394.80 F	*394.80 FL
7	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	90.00 F	*- FL
8	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	1		*REAR END PANEL	Dented	569.40 F	*569.40 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	189.70 F	*189.70 FL
11	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	10.00 FS	*10.00 FS
12	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
13	1		*BOOTLID	Repair	1,578.10 F	*- FL
14	1		*BOOTLID LOCK	Not Necessary	132.90 F	*- FL
15	1		*BOOTLID WEATHERSTRIPE	Not Necessary	145.60 F	*- FL
16	1		*HYUNDAI LOGO	Necessary	42.50 F	*42.50 FL
17	1		*ELANTRA WORDING	Necessary	48.80 F	*48.80 FL
18	1		*S EMBLEM	Necessary	45.90 F	*45.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,607.20</b>	<b>2,485.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	437.00
<b>Total Parts (\$)</b>	<b>4,607.20</b>	<b>2,048.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO SPRAY TUFF COAT	New	150.00	60.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,500.00</b>
			<b>2,800.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >