



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 1375Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (N) (CONSISTENT)	TORN	1,690.00	1,421.00
12	FRONT BUMPER CLIP (N) (CONSISTENT)	NECESSARY	60.00	30.00
1	FRONT BUMPER R/H SIDE RETAINER (N) (CONSISTENT)	NOT NECESSARY	38.00	-
1	FRONT R/H FENDER (N) (CONSISTENT)	DENTED	952.00	746.00
1	FRONT R/H FENDER EMBLEM (N) (CONSISTENT)	NECESSARY	68.00	68.00
1	FRONT R/H DOOR (N) (CONSISTENT)	TO REPAIR SEE LABOUR	1,498.00	-
1	FRONT R/H LOWER ARM (N) (CONSISTENT)	BENT	672.00	672.00
1	FRONT R/H KNUCKLE 92 (N) (CONSISTENT)	NOT NECESSARY	972.00	-
1	FRONT R/H KNUCKLE HUP (N) (CONSISTENT)	DAMAGED	532.00	532.00
1	FRONT R/H SHOCK ABSORBER (N) (CONSISTENT)	NOT NECESSARY	778.00	-
1	R/H SIDE SKIRT (N) (CONSISTENT)	TORN	492.00	492.00
10	R/H SIDE SKIRT CLIP (N) (CONSISTENT)	NECESSARY	60.00	30.00
1	FRONT R/H KNUCKLE HUP BEARIG (N) (CONSISTENT)	DAMAGED	292.00	292.00
	LESS 10% DISCOUNT		-	-428.30
			8,104.00	3,854.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT R/H "18" INCH SPORT RIM (SN) (CONSISTENT)	CUT	1,860.00	1,250.00
1	FRONT R/H "18" TYRE (SN) (CONSISTENT)	NOT NECESSARY	500.00	-
			2,360.00	1,250.00
<b><u>LABOUR</u></b>				
	TO SPRAY PAINTING.		950.00	800.00
	TO REMOVE & REFIX FRONT R/H UNDER CARRIAGE.		380.00	220.00
	TO CHECK WIRING.		50.00	30.00
	TO CONDUCT COMPUTER ALIGNMENT.		90.00	80.00
	TO REMOVE & REINSTALL FRONT BUMPER PARKING SENSOR, POSITION, CHECK & TEST FOR FUNCTIONING ALL SENSOR.		80.00	50.00
	TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK.	NOT NECESSARY	120.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC. INCLUSIVE OF THE REPAIR OF FRONT R/H DOOR.		800.00	600.00
			2,470.00	1,780.00
<b>GRAND TOTAL</b>			<b>12,934.00</b>	<b>6,884.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,500.00</b>

Report Ref No. CS/ASM21003131/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.