

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003132/T1VD3N2**Date:** 08/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00033352001

Claimant Vehicle No : SKZ6081J **Insured Vehicle No :** GBJ8098P

Date of Loss: 08/03/2021 Nature of Claim: TP Claim No: SNM21D201316/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ6081J**

Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A) Engine No: P520341933

Reg. Date: 28/01/2016 (Man. Year: 2015) Chassis No: JM6BM42A8G0330298

Colour: Grey Odometer: 96926 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,009.28	5,543.59	10,465.69	65.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	2,030.00	2,770.00	57.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,809.28	7,573.59	13,235.69	63.60
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	20,809.28	6,000.00	14,809.28	71.17
+ GST 7.00/7.00% (\$\$)	1,456.65	420.00	1,036.65	71.17
Nett Amount (\$\$)	22,265.93	6,420.00	15,845.93	71.17

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 10/03/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2021)

Parts: 143 MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ6081J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,566.00 FL	*1,005.30 FL
2	1		*BOOT LID EMBLEM	Necessary	108.90 FL	*56.30 FL
3	1		*BOOT LID EMBLEM (MAZDA 3)	Necessary	94.70 FL	*53.40 FL
4	1		*BOOT LID EMBLEM (SKYACTIVE)	Necessary	87.50 FL	*66.80 FL
5	1		*BOOT LID LAMP	N/s Cracked/O/s Not Necessary	1,130.80 FL	*265.00 FL
6	2		*BOOT LID CAR PLATE LAMP	Not Necessary	178.00 FL	*- FL
7	1		*BOOT LID OPENER HANDLE	Not Necessary	177.80 FL	*- FL
8	2		*BOOT LID STOPPER	Necessary	36.20 FL	*36.20 FL
9	1		*BOOT LID LOCK ASSY	Bent	280.40 FL	*153.00 FL
10	1		*BOOT LID LOCK CATCH	Repair	56.20 FL	*- FL
11	1		*BOOT LID WEATHERSTRIP	Cut	172.80 FL	*130.60 FL
12	1		*BOOT LID DETECTOR	Cracked	277.00 FL	*180.00 FL
13	1		*BOOT LID INNER TRIM	Not Necessary	398.70 FL	*- FL
14	2		*BOOT LID HINGE	Repair	241.60 FL	*- FL
15	1		*TAILLAMP	N/s Cracked/O/s Not Necessary	2,080.80 FL	*543.00 FL
16	2		*TAILLAMP PANEL	Repair	796.00 FL	*- FL
17	1		*REAR BUMPER	Deformed	1,023.90 FL	*689.00 FL
18	1		*REAR BUMPER SIDE RETAINER	N/s Deformed/O/s Not Necessary	159.60 FL	*79.80 FL
19	1		*REAR BUMPER REFLECTOR	N/s Cracked/O/s Not Necessary	308.60 FL	*54.59 FL
20	1		*REAR BUMPER TOWING COVER	N/s Cut/O/s Not Necessary	116.60 FL	*58.30 FL
21	1		*REAR BUMPER CENTER BRACKET	Deformed	19.80 FL	*19.80 FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	796.70 FL	*573.60 FL
23	1		*REAR BUMPER SIDE COVER	N/s Deformed/O/s Not Necessary	144.60 FL	*72.30 FL
24	1		*REAR END PANEL	Bent	854.00 FL	*469.70 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	180.10 FL	*109.40 FL
26	1		*REAR FLOOR PANEL	Repair	1,086.90 FL	*- FL
27	1		*REAR FLOOR PANEL TOP SIDE SPONGE	Cracked	389.00 FL	*325.60 FL
28	1		*REAR FLOOR PANEL TOP BOARD	Deformed	498.00 FL	*249.00 FL
29	1		*REAR WINDSCREEN MOULDING	Necessary	295.30 FL	*105.00 FL
30	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
31	1		*REAR FENDER LH	Bent	1,024.00 FL	*1,024.00 FL
32	2		*REAR FENDER INNER TRIM	Not Necessary	1,288.00 FL	*- FL
33	1		*REAR FENDER INNER COWLING	N/s Deformed/O/s Not Necessary	318.00 FL	*112.30 FL
34	1		*REAR EXHAUST SILENSER	Not Necessary	985.20 FL	*- FL
35	2		*REAR EXHAUST MOUNTING	Not Necessary	38.40 FL	*- FL
36	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	254.00 FL	*- FL
37	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
38	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
39	1		*SET BOOT LID INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
40	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*20.00 FS
41	2		*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
42	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*REAR FENDER INNER COWLING CLIP	Necessary	40.00 FS	*20.00 FS
44	1		*SET REAR FENDER INNER TRIM RH CLIP	Not Necessary	50.00 FS	*- FS
45	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
46	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
48	1		*REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
49	1		*REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					19,514.10	6,841.99
- List Item Discount on L Items 20.00/20.00% (\$)					3,504.82	1,298.40
Total Parts (\$)					16,009.28	5,543.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,600.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	900.00
3	APPLY TUFF COATING TREATMENT	New	300.00	40.00
4	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	150.00	0.00
5	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS,PERFORM DISTANCE SENSORY TESTING	New	100.00	30.00
6	RENEW REAR FLOOR INSULATOR	New	180.00	0.00
7	DISMENTLE AND INSTALL REAR SEATS,SPEAKER BOARD AND SEATS TRIMMING	New	350.00	0.00
8	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	100.00	30.00
9	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY.PERFORM AIMING AND ADJUST TO POSITION	New	120.00	30.00
10	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	150.00	40.00
11	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY,RE-ALIGN TO POSITION	New	150.00	60.00
Gross Labour Cost (\$\$)			4,800.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >