

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003133/ARS3Q2
Date: 10/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800135460
Claimant Vehicle No :	SJJ9057G	Insured Vehicle No :	SKM8188R
Date of Loss:	05/03/2021	Nature of Claim:	TP
		Claim No:	3151366657SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ9057G		
Make & Model:	LEXUS IS250, 2.5 STD FL (A)	Engine No:	4GR0516214
Reg. Date:	29/09/2008 (Man. Year: 2008)	Chassis No:	JTHBK262705087324
Colour:	Silver	Odometer:	271243 km
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Pace 6 mm	Rear Left Side:	Pace 6 mm
Front Right Side:	Pace 6 mm	Rear Right Side:	Pace 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,081.32	14,364.56	4,716.76	24.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	3,330.00	930.00	21.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,341.32	17,694.56	5,646.76	24.19
Approved Total (Overridden) (S\$)		14,200.00		

(S\$)	23,341.32	14,200.00	9,141.32	39.16
+ GST 7.00/7.00% (S\$)	1,633.89	994.00	639.89	39.16
Nett Amount (S\$)	24,975.21	15,194.00	9,781.21	39.16
+ Car Rental (12.0 x S\$120.00/day) (S\$)		1,440.00		
Nett Liability (S\$)		16,634.00		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 08/03/2021

Estimated Period of Repair: 10.0 days

Inspected At:

J-mart Motor Pte Ltd (HQ)
Blk 5 Defu Lane 10, #01-578
Singapore 539186**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (ALUMINIUM)	Buckled	2,253.10 FL	*1,859.00 FL
2	1		*FRT BUMPER	Deformed	880.00 FL	*880.00 FL
3	2		*FRT BUMPER RETAINER	Necessary	150.00 FL	*150.00 FL
4	1		*FRT BUMPER LOWER GRILLE	Deformed	105.00 FL	*105.00 FL
5	1		*FRT BUMPER REINFORCEMENT	Bent	575.00 FL	*575.00 FL
6	1		*FRT BUMPER SPONGE	Deformed	95.00 FL	*95.00 FL
7	1		*FRT BUMPER TOP RUBBER	Not Necessary	65.00 FL	*- FL
8	1		*FRT GRILLE	Cracked	473.00 FL	*473.00 FL
9	1		*FRT GRILLE LOGO	Necessary	80.00 FL	*80.00 FL
10	1		*FRT GRILLE CHROME	Cut	310.00 FL	*310.00 FL
11	1		*FRT NO PLATE BASE	Deformed	120.00 FL	*120.00 FL
12	2		*HEADLAMP	Cracked	2,400.00 FL	*2,400.00 FL
13	1		*FRT SUPPORT PANEL	Repair	1,245.00 FL	*- FL
14	1		*FRT SUPPORT PANEL TOP GARNISH	Deformed	475.00 FL	*475.00 FL
15	1		*BOOTLID	Buckled	720.00 FL	*720.00 FL
16	1		*BOOTLID LOCK	Damaged	499.00 FL	*499.00 FL
17	1		*BOOTLID W/STRIP	Cut	235.00 FL	*235.00 FL
18	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
19	1		*IS 250 EMBLEM	Necessary	75.00 FL	*75.00 FL
20	1		*LEXUS EMBLEM	Necessary	80.00 FL	*80.00 FL
21	1		*BOOTLID REFLECTOR	O/S Cut	995.60 FL	*497.80 FL
22	1		*BOOTLID INSULATOR	Not Necessary	367.80 FL	*- FL
23	14		*BOOTLID INSULATOR CLIPS	Not fitted	84.00 FL	*- FL
24	1		*REAR NO PLATE GARNISH	Deformed	1,630.00 FL	*798.00 FL
25	2		*TAILLAMP	Cut	1,138.80 FL	*1,138.80 FL
26	1		*REAR BUMPER	Deformed	890.00 FL	*890.00 FL
27	2		*REAR BUMPER RETAINER LONG	Necessary	270.00 FL	*270.00 FL
28	2		*REAR BUMPER RETAINER SHORT	Necessary	160.00 FL	*160.00 FL
29	1		*REAR BUMPER REFLECTOR	Not Necessary	240.00 FL	*- FL
30	2		*REAR BUMPER TOW HOOK COVER	Deformed	43.00 FL	*43.00 FL
31	1		*REAR BUMPER REINFORCEMENT	Bent	465.00 FL	*465.00 FL
32	2		*REAR BUMPER BRACKET	Bent	150.00 FL	*150.00 FL
33	1		*REAR BUMPER SPONGE	Cracked	135.00 FL	*135.00 FL
34	6		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
35	1		*END PANEL	Dented	765.00 FL	*765.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*END PANEL INNER GARNISH	Cracked	365.00 FL	*365.00 FL
37	1		*SPARE TYRE CARDBOARD	Deformed	415.00 FL	*415.00 FL
38	2		*REAR FENDER INNER TRIM	Not Necessary	1,169.00 FL	*- FL
39	1		*TOOL BOX	Cracked	165.80 FL	*165.80 FL
40	2		*REAR NO PLATE LAMP	Not Necessary	301.70 FL	*- FL
41	1		*FRT NO PLATE	Cracked	40.00 FS	*40.00 FS
42	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
43	1		*REVERSE SENSOR	Damaged	250.00 FS	*250.00 FS
44	2		*TAILLAMP GARNISH	Cut	128.00 FL	*128.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,164.80	15,928.40
- List Item Discount on L Items 10.00/10.00% (\$)	2,083.48	1,563.84
Total Parts (\$)	19,081.32	14,364.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	1,600.00
2	SPRAY PAINTING	New	1,800.00	1,400.00
3	TOP UP GAS	New	120.00	0.00
4	RUST PROOFING	New	80.00	80.00
5	WIIRNG (FRT & REAR)	New	60.00	60.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	80.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
Gross Labour Cost (S\$)			4,260.00	3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >