

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21003137/KQF3E2

**Date:** 14/04/2021

### REFERENCE

Insured/Claimant: Low Kai Syang Jeffrey Policy No: DMPCSNW00041892000  
Date of Loss: 04/03/2021 Nature of Claim: OD Claim No: SNM21D201256/C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ2056Y**  
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UGY2078  
Reg. Date: 26/04/2018 (Man. Year: 2018) Chassis No: MMBSTA13AJH002268  
Colour: Metallic Grey Odometer: 45828 km  
Engine Capacity: 1193 cc  
Market Value/New Car Price: S\$51,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15  
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm  
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,631.90	11,639.80	1,992.10	14.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,145.00	2,715.00	430.00	13.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,776.90</b>	<b>14,354.80</b>	<b>2,422.10</b>	<b>14.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,450.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	16,276.90	10,950.00	5,326.90	32.73
<b>+ GST 7.00/7.00% (S\$)</b>	1,139.38	766.50	372.88	32.73
<b>Nett Amount (S\$)</b>	<b>17,416.28</b>	<b>11,716.50</b>	<b>5,699.78</b>	<b>32.73</b>

### INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 10/03/2021 Inspected At:

Alan's United Auto Pte Ltd (HQ)  
Blk 7 Sin Ming Industrial Estate, #01-76  
Singapore 575642

Estimated Period of Repair: 14.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2021)
<b>Parts:</b>	143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ2056Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BUMPER FASCIA</b> (WCP)	Buckled	290.00 F	*290.00 F
2	1		<b>*FRONT BUMPER LOWER GRILLE</b> (WCP)	Cracked	120.00 F	*120.00 F
3	1		<b>*FRONT SUPPORT PANEL</b> (WCP)	Bent	500.00 F	*500.00 F
4	1		<b>*FRONT BUMPER UNDER COVER</b> (WCP)	Cracked	90.00 F	*90.00 F
5	2		<b>*BUMPER UNDER COVER SIDE GUIDE</b> (WCP)	Serviceable	36.00 F	*- F
6	1		<b>*RADIATOR ASSY</b> (WCP)	Bent	550.00 F	*550.00 F
7	1		<b>*RADIATOR LOWER HOSE</b> (WCP)	Cut	35.00 F	*35.00 F
8	1		<b>*RADIATOR FAN COWLING</b> (WCP)	Cracked	155.00 F	*155.00 F
9	1		<b>*RADIATOR FAN MOTOR</b> (WCP)	Jammed	230.00 F	*230.00 F
10	1		<b>*RADIATOR FAN BLADE</b> (WCP)	Distorted	80.00 F	*80.00 F
11	1		<b>*AIR CON CONDENSER</b> (WCP)	Bent	450.00 F	*450.00 F
12	1		<b>*FRONT O/S FENDER INNER SHIELD</b> (WCP)	Serviceable	80.00 F	*- F
13	1		<b>*ENGINE STARTER</b> (WCP)	Cracked	750.00 F	*750.00 F
14	1		<b>*ENGINE STARTER LOWER COVER</b> (WCP)	Bent	98.00 F	*98.00 F
15	1		<b>*ENGINE OIL SUMP</b> (WCP)	Bent	115.00 F	*115.00 F
16	1		<b>*ENGINE CROSS MEMBER</b> (WCP)	Bent	700.00 F	*700.00 F
17	1		<b>*ENGINE CROSS MEMBER BAR</b> (WCP)	Distorted	125.00 F	*125.00 F
18	1		<b>*O/S DRIVE SHAFT</b> (WCP)	Bent	580.00 F	*580.00 F
19	1		<b>*STEERING RACK N PINION</b> (WCP)	Bent / Jammed	900.00 F	*900.00 F
20	2		<b>*FRONT SHOCK ABSORBER</b> (WCP)	Serviceable	560.00 F	*- F
21	2		<b>*FRONT LOWER ARM</b> (WCP)	Distorted	420.00 F	*420.00 F
22	2		<b>*FRONT KNUCKLE ARM</b> (WCP)	Serviceable	520.00 F	*- F
23	2		<b>*FRONT KNUCKLE BEARING HUP</b> (WCP)	Not Necessary	310.00 F	*- F
24	2		<b>*FRONT WHEEL BEARING</b> (WCP)	Not Necessary	180.00 F	*- F
25	1		<b>*CENTRE EXHAUST BOX</b> (WCP)	Dented	570.00 F	*570.00 F
26	1		<b>*CENTRE EXHAUST HEAT SEAL (FRONT</b> (WCP)	Dented	115.00 F	*115.00 F
27	1		<b>*CENTRE EXHAUST HEAT SEAL (CTR)</b> (WCP)	Dented	95.00 F	*95.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		<b>*PETROL TANK</b> (WCP)	Dented / Cut	550.00 F	*550.00 F
29	1		<b>*REAR SPARE TYRE PANEL</b> (WCP)	Bent	580.00 F	*580.00 F
30	1		<b>*REAR AXLE</b> (WCP)	Bent	690.00 F	*690.00 F
31	2		<b>*REAR WHEEL BEARING HUP</b> (WCP)	Necessary	180.00 F	*180.00 F
32	1		<b>*FRONT BUMPER LOWER SPOILER</b>	Broken	500.00 FS	*500.00 FS
33	1		<b>*BUMPER LOWER SPOILER CTR GUIDE</b>	Necessary	150.00 FS	*150.00 FS
34	1		<b>*RADIATOR COOLANT</b>	Necessary	30.00 FS	*30.00 FS
35	5		<b>*GEAR BOX OIL (50%)</b>	Necessary	125.00 FS	*62.50 FS
36	5		<b>*ENGINE OIL (50%)</b>	Necessary	150.00 FS	*75.00 FS
37	1		<b>*ENGINE OIL FILTER</b>	Necessary	20.00 FS	*20.00 FS
38	1		<b>*ENGINE UNDER COVER CLIP</b>	Necessary	30.00 FS	*30.00 FS
39	2		<b>*HEADLAMP</b> (WCP)	Mtg Cracked	540.00 F	*540.00 F
40	1		<b>*CENTRE EXHAUST HEAT SEAL (REAR)</b> (WCP)	Dented	85.00 F	*85.00 F
41	1		<b>*FRONT STABILIZA BAR</b> (WCP)	Distorted	200.00 F	*200.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>12,484.00</b>	<b>10,660.50</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	1,147.90	979.30
<b>Total Parts (\$\$)</b>	<b>13,631.90</b>	<b>11,639.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOWING	New	60.00	50.00
2	TO REMOVE REAR SEAT, INNER TRIM, TRIM BOARD AND CARPET	New	120.00	100.00
3	TO REMOVE AIR CON CONDENSER, PIPES AND DRIER, VACUUM AND TO RECHARGE GAS	New	120.00	100.00
4	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	New	250.00	220.00
5	TO DISMANTLE AND LOWER REAR UNDERCARRIAGE	New	250.00	200.00
6	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	65.00	65.00
7	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	80.00	80.00
8	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	800.00
9	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	1,200.00	1,100.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,145.00</b>	<b>2,715.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >