

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21003140/ETF3Q2

Date: 23/03/2021

REFERENCE

Insured/Claimant:	KANAN CHIDAMBARAM	Policy No:	7210009682
Date of Loss:	08/03/2021	Nature of Claim:	OD
		Claim No:	5614793773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX6892Y		
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LELS647163
Reg. Date:	26/01/2021 (Man. Year: 2020)	Chassis No:	KNACC81CVL5392948
Colour:	Grey	Odometer:	1999 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,027.60	3,399.20	2,628.40	43.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	2,000.00	2,250.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,277.60	5,399.20	4,878.40	47.47
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	9,677.60	4,799.20	4,878.40	50.41
+ GST 7.00/7.00% (S\$)	677.43	335.94	341.49	50.41
Nett Amount (S\$)	10,355.03	5,135.14	5,219.89	50.41

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 09/03/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL-FENDER,RH	Dented	385.00 FL	*385.00 FL
2	1		*GUARD ASSY-FRONT WHEEL,RH	Not Necessary	126.00 FL	*- FL
3	1		*NIRO HYBRID EMBLEM	Necessary	30.00 FL	*30.00 FL
4	1		*GARNISH ASSY-FNDR SIDE,RH	Broken	123.00 FL	*123.00 FL
5	1		*GARNISH ASSY-FNDR SIDE,LH	Not Necessary	123.00 FL	*- FL
6	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL
7	1		*COVER-FR BUMPER UPR	Broken	637.00 FL	*637.00 FL
8	1		*COVER-FR BUMPER LWR	Cut	373.00 FL	*373.00 FL
9	1		*SKID PLATE-FR BUMPER	Not Necessary	60.00 FL	*- FL
10	1		*LIP ASSY-FRONT BUMPER	Not Necessary	38.00 FL	*- FL
11	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	28.00 FL	*- FL
12	1		*COVER ASSY-RADIATOR GRILLE UPR	Broken	40.00 FL	*40.00 FL
13	1		*GRILLE ASSY-RADIATOR	Broken	441.00 FL	*441.00 FL
14	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	68.00 FL	*- FL
15	1		*GRILLE-FRONT BUMPER	Not Necessary	131.00 FL	*- FL
16	1		*STIFFNER-FR BPR LWR	Not Necessary	116.00 FL	*- FL
17	1		*WIRING HARNESS-FR BUMPER	Not Necessary	189.00 FL	*- FL
18	1		*COVER-DAYTIME RUNNING LIGHT,LH	Not Necessary	46.00 FL	*- FL
19	1		*COVER-DAYTIME RUNNING LIGHT,RH	Not Necessary	46.00 FL	*- FL
20	1		*PIECE-FRT BUMPER GUARD LWR,LH	Broken	16.00 FL	*16.00 FL
21	1		*PIECE-FRT BUMPER GUARD LWR,RH	Cut	16.00 FL	*16.00 FL
22	1		*BRACKET-FR BUMPER SIDE,LH	Not Necessary	12.00 FL	*- FL
23	1		*BRACKET-FR BUMPER SIDE,RH	Not Necessary	12.00 FL	*- FL
24	1		*GUARD ASSY-FRONT WHEEL,LH	Not Necessary	126.00 FL	*- FL
25	1		*LAMP ASSY-HEAD,LH	Not Necessary	2,102.00 FL	*- FL
26	1		*LAMP ASSY-HEAD,RH	Cut	2,102.00 FL	*2,102.00 FL
27	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
28	1		*FRT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
29	1		*CLIP (10X) Supplementary	Necessary	10.00 FL	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,517.00	4,244.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,489.40	844.80
Total Parts (\$\$)	6,027.60	3,399.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER,RHF FENDER & FRT SUPPORT PNL.REPAIR/RE-ALIGN LHF FENDER & BONNET	New	2,000.00	800.00
2	RESPRAY FRT BUMPER,BONNET,LHF FENDER & RHF FENDER	New	1,400.00	700.00
3	REMOVE & REFIT AIRCON CONDENSER & RADIATOR	New	100.00	0.00
4	TOP UP AIRCON GAS	New	50.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	DISCONNECT MAIN BATTERY CABLE	New	120.00	0.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
9	SPRAY PAINT SKID PLATE FRONT BUMPER Supplementary	New	350.00	350.00
Gross Labour Cost (\$\$)			4,250.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >