

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003144/AGA3Q2**Date:** 19/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993808
Claimant Vehicle No :	SLB292X	Insured Vehicle No :	GBK3728H
Date of Loss:	12/02/2021	Nature of Claim:	TP
		Claim No:	6326754031SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB292X	Engine No:	3ZZ4905205
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106148607
Reg. Date:	11/11/2009 (Man. Year: 2009)	Odometer:	189091 km
Colour:	Beige		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,445.92	927.00	4,518.92	82.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,230.00	2,120.00	63.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,795.92	2,157.00	6,638.92	75.48
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	8,795.92	1,700.00	7,095.92	80.67
+ GST 7.00/7.00% (S\$)	615.71	119.00	496.71	80.67
Nett Amount (S\$)	9,411.63	1,819.00	7,592.63	80.67
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
(S\$)		2,419.00		
Liabe Amount (50.00%) (S\$)		1,209.50		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,245.95		

INSPECTION

Date of Assignment:	09/03/2021		
Date Inspected:	09/03/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

8/19/2021

Adjuster Report

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Deformed	705.10 FL	*595.00 FL
2	1		*RR BUMPER SIDE RETAINER RH	Necessary	83.90 FL	*38.00 FL
3	1		*RR BUMPER SIDE RETAINER SUPORT RH	Not Necessary	98.10 FL	*- FL
4	1		*RR BUMPER SIDE RETAINER LH	Not Necessary	83.90 FL	*- FL
5	1		*RR BUMPER SIDE RETAINER SUPORT LH	Not Necessary	98.10 FL	*- FL
6	1		*RR BUMPER BRACKET RH	Not Necessary	173.10 FL	*- FL
7	1		*RR BUMPER REFLECTOR RH	Not Necessary	113.90 FL	*- FL
8	1		*RR FENDER INNER SHIELD RH	Not Necessary	171.20 FL	*- FL
9	1		*RR FENDER RH	Repair	1,027.60 FL	*- FL
10	1		*RR TAILLAMP PANEL RH	Repair	281.20 FL	*- FL
11	1		*RR FENDER INNER TRIM RH	Not Necessary	194.40 FL	*- FL
12	1		*RR BOOTLID	Repair	972.20 FL	*- FL
13	1		*RR BOOTLID STOPED	Not Necessary	76.00 FL	*- FL
14	1		*RR BOOTLID WEATHERSTRIP	Not Necessary	216.10 FL	*- FL
15	1		*RR BOOTLID LOCK	Not Necessary	189.00 FL	*- FL
16	1		*RR BOOTLID LOCK CATCHER	Not Necessary	65.60 FL	*- FL
17	1		*RR BOOTLID OUTER HANDLE GARNISH	Not Necessary	180.40 FL	*- FL
18	1		*RR BOOTLID TOYOTA LOGO	Not Necessary	81.30 FL	*- FL
19	1		*RR BOOTLID ALTIS EMBLEM	Not Necessary	72.60 FL	*- FL
20	1		*RR BOOTLID E EMBLEM	Not Necessary	70.40 FL	*- FL
21	1		*RR BOOTLID LAMP RH	Cut	387.60 FL	*218.00 FL
22	1		*RR END PANEL	Repair	745.80 FL	*- FL
23	1		*RR TAILLAMP RH	Cracked	412.60 FL	*345.00 FL
24	1		*RR TAILLAMP GROMMET	Not Necessary	8.00 FL	*- FL
25	1		*RR WINDSCREEN MLDG	Not Necessary	99.80 FL	*- FL
26	10		*RR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
27	10		*RR FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
28	10		*RR FENDER INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
29	1		*SET RR BUMPER REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
30	1		*RR WINDSCREEN SEALANT	Not Necessary	65.00 FS	*- FS
31	1		*RR WINDSCREEN INNER SEAL	Not Necessary	40.00 FS	*- FS
32	1		*RR NUMBER PLATE	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,097.90	1,226.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,651.98	299.00
Total Parts (\$\$)	5,445.92	927.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	500.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR BUMPER ,RR END PANEL ,RR BOOTLID ,RR FENDER RH ,RR DOOR RH	New	1,200.00	600.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
4	REMOVE AND REFIX SEAL CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	200.00	0.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	50.00
6	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID	New	160.00	0.00
7	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	80.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	30.00	0.00
9	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	50.00
10	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER	New	180.00	0.00
Gross Labour Cost (\$\$)			3,350.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >