

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21003160/EVF3E2

**Date:** 04/06/2021

### REFERENCE

Insured/Claimant: KEK LIET SHENG JUSTIN (GUO LIESHENG) Policy No: 1900113533  
Date of Loss: 06/03/2021 Nature of Claim: OD Claim No: 0783541778SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM1088T**  
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH741997  
Reg. Date: 30/07/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5047682  
Colour: Black Odometer: 34239 km  
Engine Capacity: 1593 cc  
Market Value/New Car Price: S\$74,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm  
Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,235.60	4,051.20	1,184.40	22.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,440.00	5,090.00	1,350.00	20.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,675.60</b>	<b>9,141.20</b>	<b>2,534.40</b>	<b>21.71</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>11,375.60</b>	<b>8,841.20</b>	<b>2,534.40</b>	<b>22.28</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>796.29</b>	<b>618.88</b>	<b>177.41</b>	<b>22.28</b>
<b>Nett Amount (S\$)</b>	<b>12,171.89</b>	<b>9,460.08</b>	<b>2,711.81</b>	<b>22.28</b>

### INSPECTION

Date of Assignment: 10/03/2021  
Date Inspected: 10/03/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 12.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Broken	2,210.00 FL	*2,210.00 FL
3	1		*WIRING ASSY-T/M GND	Not Necessary	33.00 FL	*- FL
4	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
5	1		*INSULATOR-FENDER LH	Crushed	27.00 FL	*27.00 FL
6	1		*PANEL-FENDER, LH	Dented	430.00 FL	*430.00 FL
7	1		*INSULATOR-FENDER LH	Not Necessary	27.00 FL	*- FL
8	1		*GUARD ASSY-FRONT WHEEL, LH	Crushed	95.00 FL	*95.00 FL
9	1		*GARNISH-RADIATOR GRILLE	Crushed	38.00 FL	*38.00 FL
10	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
11	1		*GRILLE-FRONT BUMPER	Cut	485.00 FL	*485.00 FL
12	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
13	1		*LAMP ASSY-SIDE REPEATER, LH	Cut	143.00 FL	*143.00 FL
14	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
15	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
16	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
17	1		*WIRING ASSY-BUMPER EXTENSION	Not Necessary	207.00 FL	*- FL
18	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
19	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
20	1		*PANEL ASSY-FNDR APRON, LH	Repair	538.00 FL	*- FL
21	1		*PNL-FENDER APRON UPR OTR, LH	Repair	30.00 FL	*- FL
22	1		*BRACKET ASSY-FENDER & BPR MTG,	Not Necessary	14.00 FL	*- FL
23	1		*MOULDING-FRONT BUMPER, LH (Supplementary)	Cut	216.00 FL	*216.00 FL
24	7		*CLIPS (Supplementary)	Necessary	7.00 FL	*7.00 FL
25	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,532.00</b>	<b>5,059.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,296.40	1,007.80
<b>Total Parts (\$\$)</b>	<b>5,235.60</b>	<b>4,051.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER, FRT LH FENDER, FRT LH INNER FENDER, SUPPORT & AFFECTED AREA. REPAIR ON FRT LH DOOR & LH ROCKER PANEL	New	2,400.00	1,600.00
2	PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH INNER FENDER, FRT LH DOOR, LH ROCKER PANEL & BONNET	New	2,100.00	1,750.00
3	TO REMOVE & INSTALL FRONT PARKING ASSIST	New	120.00	80.00
4	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
5	TO TOP UP AIRCON GAS	New	80.00	80.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	0.00
8	PERFORM RUST PREVENTION	New	120.00	40.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	REPAIR ON LH FRONT WHEEL HOUSING,LH SIDE SILL,LH FRONT PILLAR,LH FRONT DOOR (\$400 +\$200) (Supplementary)	New	600.00	600.00
12	RESPRAY ON LH FRONT A PILLAR (Supplementary)	New	350.00	350.00
13	REPAIR ON FRONT WIRING (Supplementary)	New	200.00	200.00
			<b>Gross Labour Cost (\$\$)</b>	<b>5,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >