



**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE)
	Reg No/Reg Date	SMM1088T / 30/07/201
	Date In/Mileage	10/03/2021/ 0
	Chassis No	KNAF3416MK5047682
	Engine No	G4FGKH741997
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/03/2021/ 12:48	QUK	282 / Kevin Leong	30266

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT LH FENDER, FRT LH INNER FENDER, SUPPORT & AFFECTED AREA REPAIR ON FRT LH DOOR & LH ROCKER PANEL	4 X 400			1600 2400.00
E PNT98000 PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH INNER FENDER, FRT LH DOOR, LH ROCKER PANEL & BONNET	6 X 350	1750		2100.00
E PNT88000 TO REMOVE & INSTALL FRONT PARKING ASSIST				80 120.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				80 120.00
M SUNDRY TO TOP UP AIRCON GAS				80 120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				80 80.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				40 120.00
M SUNDRY PERFORM RUST PREVENTION				30 30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				20 50.00
M SUNDRY SUNDRIES				
M LAMP ASSY-HEAD, LH / OR ? X KIA	1.00	2210.00	20.00	1768.00
M WIRING ASSY-T/M GND	1.00	33.00	20.00	26.40
M CARRIER ASSY-FRONT END MODULE / OR	1.00	675.00	20.00	540.00
M INSULATOR-FENDER LH / CR4	1.00	27.00	20.00	21.60
M PANEL-FENDER, LH / 00 ? X KIA	1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH / ? X KIA	1.00	27.00	20.00	21.60
M GUARD ASSY-FRONT WHEEL, LH / CR4	1.00	95.00	20.00	76.00

*(photo)*  
**Estimate**

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE) Reg No/Reg Date SMM1088T / 30/07/201 Date In/Mileage 10/03/2021/ 0 Chassis No KNAF3416MK5047682 Engine No G4FGKH741997 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/03/2021/ 12:48	QUK	282 / Kevin Leong	30266

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH-RADIATOR GRILLE ✓ CRU	1.00	38.00	20.00	30.40
M COVER-FR BUMPER ✓ BR	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER X H/W cut	1.00	485.00	20.00	388.00
M LAMP ASSY-FRONT FOG, LH X NM	1.00	303.00	20.00	242.40
M LAMP ASSY-SIDE REPEATER, LH X NM CUT	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH ? X NM	1.00	14.00	20.00	11.20
M STIFFNER-FR BPR LWR X NM	1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG ✓ BR	1.00	22.00	20.00	17.60
M WIRING ASSY-BUMPER EXTENSION ✓ X NM	1.00	207.00	20.00	165.60
M ULTRASONIC SENSOR ASSY-P.A.S X NM	1.00	163.00	20.00	130.40
M ORNAMENT-KIA NO.115 ✓	1.00	32.00	20.00	25.60
M PANEL ASSY-FNDR APRON, LH ✓ X R	1.00	538.00	20.00	430.40
M PNL-FENDER APRON UPR OTR, LH ✓ X R	1.00	30.00	20.00	24.00
M BRACKET ASSY-FENDER & BPR MTG. ✓ X NM	1.00	14.00	20.00	11.20

# Estimate

Steve CLKK) 00-NM AL  
 10/3/21, 2.30pm EXCESS ?  
 P/P  
 My R sy  
 12 # dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by: [Signature] (Secondary item(s) must be resurveyed and is subject to final approval from Insurance Company)

Acknowledged by Repairer  
 Signature:  
 Date:

Authorized signatory and company stamp

	Nett	10,326.40
7% GST on	10326.40	722.85
	<b>Total Payable</b>	<b>11,049.25</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.