



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|--|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE |
| | Reg No/Reg Date | SMM1088T / 30/07/201 |
| | Date In/Mileage | 10/03/2021/ 0 |
| | Chassis No | KNAF3416MK5047682 |
| | Engine No | G4FGKH741997 |
| | Make/Model | KIA/CERATO 1.6 A SR SX G335 |
| | Colour/Trim | ABT PLATINUM GRAPHI/ WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | | |
|---------------------------------|--|-------------------|-----|-------------------|--------|------------|-------|---------|---------|
| LAX00000 | Credit | 10/03/2021/ 12:48 | QUK | 282 / Kevin Leong | 30266 | | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount | |
| E PNT88000 | REPLACE FRT BUMPER, FRT LH FENDER, FRT LH INNER FENDER, SUPPORT & AFFECTED AREA REPAIR ON FRT LH DOOR & LH ROCKER PANEL | | | | | | | | 2400.00 |
| E PNT98000 | PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH INNER FENDER, FRT LH DOOR, LH ROCKER PANEL & BONNET | | | | | | | | 2100.00 |
| E PNT88000 | TO REMOVE & INSTALL FRONT PARKING ASSIST | | | | | | | | 120.00 |
| E PNT88000 | REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR | | | | | | | | 120.00 |
| M SUNDRY | TO TOP UP AIRCON GAS | | | | | | | | 80.00 |
| A WHEELALIGNMENTBP | To Conduct Computerize Full Wheel Alignment | | | | | | | | 120.00 |
| M SUNDRY | TO APPLY SEALANT ON AFFECTED AREA | | | | | | | | 80.00 |
| M SUNDRY | PERFORM RUST PREVENTION | | | | | | | | 120.00 |
| A 54900099 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | | 30.00 |
| A 10028901 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | | | | 120.00 |
| M SUNDRY | SUNDRIES | | | | | | | | 50.00 |
| M LAMP ASSY-HEAD,LH | | | | | 1.00 | 2210.00 | 20.00 | 1768.00 | |
| M WIRING ASSY-T/M GND | | | | | 1.00 | 33.00 | 20.00 | 26.40 | |
| M CARRIER ASSY-FRONT END MODULE | | | | | 1.00 | 675.00 | 20.00 | 540.00 | |
| M INSULATOR-FENDER LH | | | | | 1.00 | 27.00 | 20.00 | 21.60 | |
| M PANEL-FENDER,LH | | | | | 1.00 | 430.00 | 20.00 | 344.00 | |
| M INSULATOR-FENDER LH | | | | | 1.00 | 27.00 | 20.00 | 21.60 | |
| M GUARD ASSY-FRONT WHEEL,LH | | | | | 1.00 | 95.00 | 20.00 | 76.00 | |

Confirm & accepted by

 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|--|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE |
| | Reg No/Reg Date | SMM1088T / 30/07/201 |
| | Date In/Mileage | 10/03/2021/ 0 |
| | Chassis No | KNAF3416MK5047682 |
| | Engine No | G4FGKH741997 |
| | Make/Model | KIA/CERATO 1.6 A SR SX G335 |
| | Colour/Trim | ABT PLATINUM GRAPHI/ WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---------------------------------|--------------------------------|-------------------|------------|-------------------|--------|
| LAX00000 | Credit | 10/03/2021/ 12:48 | QUK | 282 / Kevin Leong | 30266 |
| Description of Goods / Services | | | | | |
| | | Qty | Unit Price | Disc% | Amount |
| M | GARNISH-RADIATOR GRILLE | 1.00 | 38.00 | 20.00 | 30.40 |
| M | COVER-FR BUMPER | 1.00 | 633.00 | 20.00 | 506.40 |
| M | GRILLE-FRONT BUMPER | 1.00 | 485.00 | 20.00 | 388.00 |
| M | LAMP ASSY-FRONT FOG,LH | 1.00 | 303.00 | 20.00 | 242.40 |
| M | LAMP ASSY-SIDE REPEATER,LH | 1.00 | 143.00 | 20.00 | 114.40 |
| M | AIR DUCT-FR BUMPER,LH | 1.00 | 14.00 | 20.00 | 11.20 |
| M | STIFFNER-FR BPR LWR | 1.00 | 114.00 | 20.00 | 91.20 |
| M | BRACKET-FR BUMPER UPR SIDE MTG | 1.00 | 22.00 | 20.00 | 17.60 |
| M | WIRING ASSY-BUMPER EXTENSION | 1.00 | 207.00 | 20.00 | 165.60 |
| M | ULTRASONIC SENSOR ASSY-P.A.S | 1.00 | 163.00 | 20.00 | 130.40 |
| M | ORNAMENT-KIA NO.115 | 1.00 | 32.00 | 20.00 | 25.60 |
| M | PANEL ASSY-FNDR APRON,LH | 1.00 | 538.00 | 20.00 | 430.40 |
| M | PNL-FENDER APRON UPR OTR,LH | 1.00 | 30.00 | 20.00 | 24.00 |
| M | BRACKET ASSY-FENDER & BPR MTG, | 1.00 | 14.00 | 20.00 | 11.20 |

Confirm & accepted by

| | | |
|----------------------|-----------------|------------------|
| | Nett | 10,326.40 |
| 7% GST on | 10326.40 | 722.85 |
| Total Payable | | 11,049.25 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.