

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21003165/KBS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMP8377Y	Insured Vehicle No :	SLM4349H
Date of Loss:	05/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000970

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8377Y		
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Engine No:	G4FGKU200987
Reg. Date:	18/10/2019 (Man. Year: 2019)	Chassis No:	KMHD841CMLU965799
Colour:	Metallic Grey	Odometer:	18400 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,377.92	8,549.28	6,828.64	44.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	4,990.00	2,730.00	2,260.00	45.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,378.92	11,290.28	9,088.64	44.60
+ GST 7.00/7.00% (S\$)	1,426.53	790.32	636.21	44.60

Nett Amount (S\$)	21,805.45	12,080.60	9,724.85	44.60
+ Car Rental (22.0 x S\$117.70/day) (S\$)		2,589.40		
+ Doc/Search Fee (S\$)		14.98		
Nett Liability (S\$)		14,684.98		
Global Sum Settlement (S\$)		14,600.00		

INSPECTION

Date of Assignment:	10/03/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	12/03/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	9.0 days		

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP8377Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear number plate with casing	Dented	35.00 FS	*35.00 FS
2	1		*Rear bumper	Buckled	459.40 FL	*459.40 FL
3	1		*Rear bumper clips	Necessary	15.00 FL	*15.00 FL
4	1		*Rear bumper side retainer LH	Serviceable	29.40 FL	*- FL
5	1		*Rear bumper side retainer RH	Serviceable	29.40 FL	*- FL
6	1		*Rear bumper reinforcement	Cracked	294.80 FL	*294.80 FL
7	1		*Rear bumper lower skirt	Cracked	353.50 FL	*353.50 FL
8	1		*Rear bumper reflector LH	Serviceable	201.50 FL	*- FL
9	1		*Rear bumper reflector RH	Serviceable	201.50 FL	*- FL
10	1		*Reverse sensor	Dented	240.00 FS	*240.00 FS
11	1		*Taillamp LH	Serviceable	1,052.10 FL	*- FL
12	1		*Taillamp RH	Serviceable	1,052.10 FL	*- FL
13	1		*Taillamp clips	Not Necessary	9.80 FL	*- FL
14	1		*Taillamp lower panel LH	Repair	193.10 FL	*- FL
15	1		*Taillamp lower panel RH	Repair	193.10 FL	*- FL
16	1		*Rear end panel	Repair	454.60 FL	*- FL
17	1		*Rear end panel garnish	Serviceable	59.80 FL	*- FL
18	1		*Rear end panel garnish clips	Not Necessary	10.00 FL	*- FL
19	1		*Bootlid cover	Bent	1,782.40 FL	*1,782.40 FL
20	1		*Bootlid lock	Repair	116.20 FL	*- FL
21	1		*Bootlid weatherstrip	Serviceable	92.50 FL	*- FL
22	1		*Bootlid inner trim centre	Serviceable	146.80 FL	*- FL
23	1		*Emblem	Necessary	196.20 FL	*196.20 FL
24	1		*AVANTE	Necessary	31.20 FL	*31.20 FL
25	1		*Reverse camera	Serviceable	826.10 FL	*- FL
26	1		*front number plate with casing	Bent	35.00 FS	*35.00 FS
27	1		*Front bumper	Cracked	474.40 FL	*474.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*Front bumper clips	Necessary	20.00 FL	*20.00 FL
29	1		*front bumper reinforcement	Repair	695.80 FL	*- FL
30	1		*Front bumper side retainer LH	Serviceable	13.70 FL	*- FL
31	1		*Front bumper side retainer RH	Distorted	13.70 FL	*13.70 FL
32	1		*Front bumper sponge	Cracked	110.70 FL	*110.70 FL
33	1		*Front bumper beam lower	Repair	119.00 FL	*- FL
34	1		*Front bumper protector center	Serviceable	115.40 FL	*- FL
35	1		*Front bumper protector LH	Serviceable	115.40 FL	*- FL
36	1		*Front bumper protector RH	Serviceable	115.40 FL	*- FL
37	1		*Front bumper tow cover	Serviceable	8.00 FL	*- FL
38	1		*Front bumper lower lip	Serviceable	71.70 FL	*- FL
39	1		*Fog lamp LH	Serviceable	164.80 FL	*- FL
40	1		*Fog lamp RH	Serviceable	164.80 FL	*- FL
41	1		*Fog lamp side grille LH	Serviceable	33.60 FL	*- FL
42	1		*Fog lamp side grille RH	Serviceable	33.60 FL	*- FL
43	1		*Headlamp LH	Serviceable	1,756.40 FL	*- FL
44	1		*Headlamp RH	Cracked	1,756.40 FL	*1,756.40 FL
45	1		*Front support panel	Cracked	949.30 FL	*949.30 FL
46	1		*Bonnet	Bent	1,970.70 FL	*1,741.20 FL
47	1		*Bonnet lock	Repair	129.90 FL	*- FL
48	1		*Grille emblem	Necessary	26.20 FL	*26.20 FL
49	1		*Front support top garnish	Cracked	84.50 FL	*84.50 FL
<u>Supplementary #1</u>						
50	1		*Front bumper upper support bracket RH	Cracked	19.00 FL	*19.00 FL
51	1		*Front number plate garnish	Dented	19.00 FL	*19.00 FL
52	1		*Radiator grille	Cracked	1,214.00 FL	*1,089.20 FL
53	1		*Air guide RH	Dented	39.00 FL	*39.00 FL
54	1		*Headlamp lower bracket RH	Cracked	21.00 FL	*21.00 FL
55	1		*Headlamp lower bracket clips	Necessary	10.00 FL	*10.00 FL
56	1		*Condenser	Bent	745.00 FL	*745.00 FL
57	1		*Headlamp absorber	Cracked	24.00 FL	*48.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,144.90	10,609.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,766.98	2,059.82
Total Parts (\$\$)	15,377.92	8,549.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT /WELD AND PANEL BEAT REAR END PANEL, REAR BUMPER, BOOTLID, FRONT BUMPER, BONNET, FRONT PANEL , REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	2,400.00	1,200.00
2	TO PUTYY ,RESPRAY ON REAR BUMPER,END PANEL,BOOTLID, FRONT BUMPER, BONNET , FRONT PANEL , DAMAGES AND AFFECTED AREAS	New	2,000.00	1,250.00
3	TO CHECK LIGHTING AND WIRING	New	120.00	40.00
4	TO INSTALL REVERSE SENSOR	New	120.00	80.00
5	TO TRANSFER BOOTLID PARTS AND MECHANISMS TO NEW BOOTLID	New	150.00	60.00
6	TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS	New	200.00	100.00
Gross Labour Cost (\$)			4,990.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >