

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003168/UBA3Q2
Date: 02/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263040
Claimant Vehicle No :	SMV9258U	Insured Vehicle No :	SMR5992E
Date of Loss:	09/03/2021	Nature of Claim:	TP
		Claim No:	5252819901SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV9258U		
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Engine No:	L15B31190217
Reg. Date:	11/08/2016 (Man. Year: 2016)	Chassis No:	JHMGK5850HX200340
Colour:	Red	Odometer:	26593 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,956.58	1,039.70	1,916.88	64.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,600.00	680.00	29.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,236.58	2,639.70	2,596.88	49.59
+ GST 7.00/7.00% (S\$)	366.56	184.78	181.78	49.59

Nett Amount (S\$)	5,603.14	2,824.48	2,778.66	49.59
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,186.48		
Global Sum Settlement (S\$)		3,150.00		

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOCK (WCP)	Serviceable	129.20 F	*- F
2	1		*TAILGATE WEATHERSTRIP (WCP)	Not Necessary	92.30 F	*- F
3	1		*TAILGATE EMBLEM (LOGO) (WCP)	Not Necessary	24.70 F	*- F
4	1		*TAILGATE CHROME (WCP)	Not Necessary	229.70 F	*- F
5	1		*END PANEL (WCP)	Repair	373.50 F	*- F
6	1		*REAR BUMPER RETAINER LH (WCP)	Not Necessary	15.70 F	*- F
7	1		*REAR BUMPER RETAINER RH (WCP)	Not Necessary	15.70 F	*- F
8	1		*REAR BUMPER BRACKET LH (WCP) (NPA)	Not Necessary	0.00 F	*- F
9	1		*REAR BUMPER BRACKET LH (WCP) (NPA)	Not Necessary	0.00 F	*- F
10	1		*REAR BUMPER REINFORCEMENT (WCP)	No such part	0.00 F	*- F
11	1		*TAILGATE (WCP)	Badly Dented	400.00 F	*400.00 F
12	1		*TAILGATE LOGO -JAZZ (WCP)	Necessary	12.00 F	*12.00 F
13	1		*TAILGATE WINDSCREEN MOULDING (WCP)	Necessary	70.00 F	*70.00 F
14	1		*REAR BUMPER (WCP)	Dented	200.00 F	*200.00 F
15	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
16	1		*REVERSE CAMERA	Not Necessary	580.00 FS	*- FS
17	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
18	1		*SET REVERSE SENSOR	Shorted	560.00 FS	*200.00 FS
19	1		*SMART BUZZY (WCP)	Shorted	45.00 F	*45.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,795.80	967.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	160.78	72.70
Total Parts (\$\$)	2,956.58	1,039.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	800.00
3	ANTI-RUST COATING	New	150.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			2,280.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >