



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 6177J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,855.30	1,620.00
2	REAR BUMPER SIDE RETAINER @\$60.30 (CONSISTENT)	NECESSARY	120.60	120.60
2	REAR BUMPER SIDE BRACKET @\$90.80 (CONSISTENT)	NOT NECESSARY	181.60	-
1	REAR BUMPER LOWER SPOILER (CONSISTENT)	DEFORMED	633.40	633.40
1	REAR BUMPER TOWING COVER (CONSISTENT)	DEFORMED	80.00	80.00
1	REAR BUMPER CENTRE BRACKET (CONSISTENT)	CRACKED	303.41	303.41
2	REAR BUMPER REFLECTOR @\$130.50 (CONSISTENT)	NOT NECESSARY	261.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	655.20	650.00
2	REAR BUMPER REVERSE SENSOR @\$320.20 (CONSISTENT)	DAMAGED	640.40	450.00
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	885.00	-
1	END PANEL INNER GARNISH (CONSISTENT)	NOT NECESSARY	225.50	-
	LESS 10% DISCOUNT		-584.14	-385.74
			5,257.27	3,471.67
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	50.00	50.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
1	REVERSE CAMERA (SN) (CONSISTENT)	CRACKED	550.00	380.00
			810.00	460.00
<b><u>LABOUR</u></b>				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF END PANEL .		1,000.00	400.00
	TO SPRAY PAINT AFFECTED AREA .		1,000.00	400.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.00	50.00
			2,490.00	970.00
GRAND TOTAL			8,557.27	4,901.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CC4/ASM21003170/Ars3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.