

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21003177/ETF3E2

Date: 12/04/2021

REFERENCE

Insured/Claimant:	ISMANI BIN KASIMI	Policy No:	1900259586-01		
Date of Loss:	10/03/2021	Nature of Claim:	OD	Claim No:	1675587927SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR574L		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11AA2736
Reg. Date:	17/12/2019 (Man. Year: 2018)	Chassis No:	GF7W0600199
Colour:	Grey	Odometer:	33605 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,008.18	8,157.36	850.82	9.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,730.00	4,590.00	1,140.00	19.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,738.18	12,747.36	1,990.82	13.51
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,438.18	12,447.36	1,990.82	13.79
+ GST 7.00/7.00% (S\$)	1,010.67	871.32	139.35	13.79
Nett Amount (S\$)	15,448.85	13,318.68	2,130.17	13.79

INSPECTION

Date of Assignment:	10/03/2021	
Date Inspected:	10/03/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, LH	Broken	1,948.00 FL	*1,948.00 FL
3	1		*HEADLAMP ASSY, RH	Broken	1,948.00 FL	*1,948.00 FL
4	1		*HORN, THEFT PROTECTION	Not Necessary	92.00 FL	*- FL
5	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
6	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
7	1		*COVER, FR BUMPER	Broken	361.00 FL	*361.00 FL
8	1		*EXTENSION, FR BUMPER	Cut	517.00 FL	*517.00 FL
9	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 FL	*18.00 FL
10	1		*BRACKET, FR BUMPER SIDE, RH	Broken	18.00 FL	*18.00 FL
11	1		*BAR, FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
12	1		*REINFORCEMENT, FR BUMPER	Bent	505.00 FL	*505.00 FL
13	1		*REINFORCEMENT, FR BUMPER	Bent	135.00 FL	*135.00 FL
14	1		*REINFORCEMENT, FR BMPR SIDE	Bent	22.00 FL	*22.00 FL
15	1		*REINF, FR BUMPER SIDE, RH	Bent	69.00 FL	*69.00 FL
16	1		*REINF, FR BUMPER SIDE, LH	Bent	60.00 FL	*60.00 FL
17	1		*COVER, HEADLAMP SUPT PANEL	Cut	50.00 FL	*50.00 FL
18	1		*GRILLE ASSY, RADIATOR	Broken	550.00 FL	*550.00 FL
19	1		*COVER, FR BUMPER	Broken	25.00 FL	*25.00 FL
20	1		*BRACKET, RADIATOR GRILLE, LH	Bent	13.00 FL	*13.00 FL
21	1		*BRACKET, RADIATOR GRILLE, RH	Bent	17.00 FL	*17.00 FL
22	1		*HOOD	Dented	980.00 FL	*980.00 FL
23	1		*WEATHERSTRIP, HOOD	Not Necessary	41.00 FL	*- FL
24	1		*WEATHERSTRIP, HOOD	Not Necessary	40.00 FL	*- FL
25	1		*HINGE, HOOD, LH	Not Necessary	68.00 FL	*- FL
26	1		*HINGE, HOOD, RH	Not Necessary	68.00 FL	*- FL
27	1		*LATCH, HOOD	Not Necessary	76.00 FL	*- FL
28	1		*FENDER, FR LH	Bent	622.00 FL	*622.00 FL
29	1		*FENDER, FR RH	Bent	622.00 FL	*622.00 FL
30	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	183.00 FL	*183.00 FL
31	1		*PNL, HEADLAMP SUPT, UPR LH	Not Necessary	58.00 FL	*- FL
32	1		*PNL, HEADLAMP SUPT, UPR RH	Not Necessary	58.00 FL	*- FL
33	1		*PANEL, HEADLAMP SUPPORT, LWR	Not Necessary	107.00 FL	*- FL
34	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	164.00 FL	*- FL
35	1		*SHIELD, FR WHEELHOUSE, RH	Not Necessary	164.00 FL	*- FL
36	1		*GARNISH, FR BUMPER SIDE	Cut	112.00 FL	*112.00 FL
37	1		*MOULDING, FR WHEEL ARCH, LH (Supplementary)	Necessary	160.00 FL	*160.00 FL
38	1		*MOULDING, FR WHEEL ARCH, RH (Supplementary)	Necessary	160.00 FL	*160.00 FL
39	20		*CLIP, RR BUMPER (Supplementary)	Necessary	60.00 FL	*60.00 FL
40	10		*CLIP, FR BUMPER (Supplementary)	Necessary	40.00 FL	*40.00 FL
41	20		*CLIP, ENG ROOM COVER (Supplementary)	Necessary	40.00 FL	*40.00 FL
42	6		*RIVET, FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL
43	1		*FACE, FR BUMPER (Supplementary)	Necessary	863.00 FL	*863.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,684.00	10,588.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,675.82	2,430.64
Total Parts (\$\$)	9,008.18	8,157.36

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BOTH FRT FENDER, SUPPORT, BONNET & AFFECTED AREA. REPAIR ON BOTH FRT DOOR	New	3,150.00	2,250.00
2	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & BOTH FRT DOOR	New	2,100.00	2,100.00
3	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	0.00
4	TO TOP UP AIRCON GAS	New	80.00	0.00
5	PERFORM RUST PREVENTION	New	80.00	40.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
Gross Labour Cost (\$\$)			5,730.00	4,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >