

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21003178/EQF3E2

Date: 30/03/2021

REFERENCE

Insured/Claimant:	LE MY DIEP	Policy No:	1800139117		
Date of Loss:	10/03/2021	Nature of Claim:	OD	Claim No:	5194474784SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF7496X	Engine No:	G4FGJH709505
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5020921
Reg. Date:	23/11/2018 (Man. Year: 2018)	Odometer:	47603 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$71,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	NFERA 5 mm	Rear Left Side:	NFERA 5 mm
Front Right Side:	NFERA 5 mm	Rear Right Side:	NFERA 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,070.00	1,982.40	2,087.60	51.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	2,000.00	520.00	20.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,590.00	3,982.40	2,607.60	39.57
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	6,290.00	3,682.40	2,607.60	41.46
+ GST 7.00/7.00% (S\$)	440.30	257.77	182.53	41.46
Nett Amount (S\$)	6,730.30	3,940.17	2,790.13	41.46

INSPECTION

Date of Assignment:	10/03/2021	
Date Inspected:	10/03/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FRT RIGHT RIM	Cut	360.00 FS	*360.00 FS
3	1		*COVER-FR BUMPER	Repair	633.00 F	*- FL
4	1		*MOULDING-FRONT BUMPER, RH	Cut	36.00 F	*36.00 FL
5	1		*GRILLE-FRONT BUMPER	Not Necessary	262.00 F	*- FL
6	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 F	*- FL
7	1		*PANEL-FENDER, RH	Dented	430.00 F	*430.00 FL
8	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 F	*- FL
9	1		*LAMP ASSY-HEAD, RH	Broken	1,219.00 F	*1,219.00 FL
10	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 F	*- FL
11	1		*ORNAMENT-KIA NO 115 (Supplementary)	Necessary	32.00 F	*32.00 FL
12	1		*ARM COMPLETE-FR LWR,RH (Supplementary)	Bent	286.00 F	*286.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,070.00	2,383.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	400.60
Total Parts (\$\$)	4,070.00	1,982.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL	New	1,200.00	800.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH	New	700.00	700.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TRANSFER FRT RIGHT RIM	New	30.00	30.00
7	REMOVE & REPLACE RH FRONT LOWER ARM COMPLETE (Supplementary)	New	200.00	200.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			2,520.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >