

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003186/ABA3Q2
Date: 05/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070092145
Claimant Vehicle No :	SLQ1201Z	Insured Vehicle No :	GBE4392S
Date of Loss:	06/03/2021	Nature of Claim:	TP
		Claim No:	3576308394SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1201Z		
Make & Model:	HONDA CIVIC, 1.6 VTI (A)	Engine No:	R16B22000271
Reg. Date:	28/06/2017 (Man. Year: 2017)	Chassis No:	MRHFC5650HT000180
Colour:	White	Odometer:	51678 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,985.68	3,490.48	2,495.20	41.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	1,710.00	3,990.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,685.68	5,200.48	6,485.20	55.50
Approved Total (Overridden) (S\$)		4,100.00		

Nett Amount (S\$)	11,685.68	4,100.00	7,585.68	64.91
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,067.45		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 16/03/2021

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	674.60 FL	*674.60 FL
2	1		*FRONT BUMPER FOGLAMP COVER GARNISH LH	Not Necessary	43.10 FL	*- FL
3	1		*FRONT BUMPER RETAINER	N/S Necessary	67.20 FL	*33.60 FL
4	1		*FRONT FENDER LH	Dented	480.40 FL	*480.40 FL
5	1		*FRONT FENDER SIGNAL LAMP LH	Cut	49.60 FL	*49.60 FL
6	1		*FRONT FENDER INNER SPONGE LH	Not Necessary	76.40 FL	*- FL
7	1		*FRONT FENDER COWLING LH	Torn	132.10 FL	*132.10 FL
8	1		*HEADLAMP (LED) LH	Cracked	894.90 FL	*894.90 FL
9	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	48.30 FL	*- FL
10	1		*HEADLAM TOP MOULDING (BLACK) LH	Not Necessary	144.20 FL	*- FL
11	1		*RESONATOR BOX	Not Necessary	104.80 FL	*- FL
12	1		*FRONT GRILLE	Not Necessary	171.20 FL	*- FL
13	1		*FRONT GRILLE LOGO	Not Necessary	38.40 FL	*- FL
14	1		*FRONT GRILLE CHROME	Not Necessary	130.40 FL	*- FL
15	1		*FRONT WHEEL SPORT RIM LH	Cut	769.20 FL	*769.20 FL
16	1		*FRONT ABS SENSOR RH	Not Necessary	149.20 FL	*- FL
17	1		*FRONT SHOCK ABSORBER LH	Not Necessary	368.20 FL	*- FL
18	1		*FRONT KNUCKLE ARM LH	Not Necessary	284.40 FL	*- FL
19	1		*FRONT LOWER ARM LH	Not Necessary	439.30 FL	*- FL
20	1		*FRONT DOOR SIDE MIRROR LH	Damaged	596.80 FL	*596.80 FL
21	1		*SIDE SKIRT LH	Deformed	369.40 FL	*369.40 FL
22	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
23	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
24	1		*SET FRONT BUMPER FOGLAMP COVER GARNISH CLIP LH	Not Necessary	60.00 FS	*- FS
25	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	80.00 FS	*30.00 FS
26	1		*SET FRONT GRILLE CLIP	Not Necessary	50.00 FS	*- FS
27	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
28	1		*SET SIDE SKIRT CLIP	Necessary	80.00 FS	*30.00 FS
29	1		*FRONT WHEEL TYRE RH	Cut	650.00 FS	*200.00 FS
30	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,192.10	4,290.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,206.42	800.12
Total Parts (\$)	5,985.68	3,490.48

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	WIRING CHECK	New	250.00	30.00
4	REFOCUS HEADLAMP BEAM	New	80.00	0.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
7	FOUR WHEEL ALIGNMENT	New	120.00	80.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	RESET ABS LIGHT	New	350.00	0.00
10	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,700.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >