



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTV 1692

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SET FAIRING ASSY (CONSISTENT)	CRACKED	958.00	725.00
1	FRONT FORK ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	688.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	220.00	-
1	FRONT LOWER COVER (CONSISTENT)	CUT	150.00	145.00
1	FRONT INNER COVER (CONSISTENT)	CRACKED	180.00	162.00
1	ENGINE COVER (CONSISTENT)	NOT NECESSARY	95.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	68.00	-
1	FRONT WHEEL RIM (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	148.00	-
1	HANDLE-BAR (CONSISTENT)	BENT	90.00	90.00
2	HANDLE-BAR ENDS (CONSISTENT)	N/S CUT	90.00	30.00
1	SET MIRROR (CONSISTENT)	SERVICEABLE	65.00	-
1	FRONT SIGNALS (N/S)(CONSISTENT)	BROKEN	180.00	75.00
1	REAR SIGNAL (N/S)(CONSISTENT)	CUT	140.00	75.00
1	FOOTSTEP PANEL (CONSISTENT)	NOT NECESSARY	220.00	-
1	STEP LOWER COVER (CONSISTENT)	CRACKED	145.00	145.00
1	HEADLAMP ASSY (ADDITIONAL)(CONSISTENT)	CRACKED	400.00	285.00
	LESS 10% DISCOUNT		-411.70	-173.20
			3,705.30	1,558.80
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)(CONSISTENT)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)(CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)(CONSISTENT)	NOT NECESSARY	95.00	-
1	SET STICKER (SN)(CONSISTENT)	NECESSARY	100.00	60.00
			309.00	60.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE .		30.00	30.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-

Report Ref No. CC4/ASM21003189/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR BODY FRAME .	NOT NECESSARY	380.00	-
	TO PROVIDE LABOUR .INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY .		460.00	280.00
			950.00	310.00
GRAND TOTAL			4,964.30	1,928.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CC4/ASM21003189/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.