

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003190/QVD3E2

Date: 23/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMF2039R

Insured Vehicle No : GBJ8750P

Date of Loss: 08/03/2021

Nature of Claim: TP

Claim No: 4409077271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF2039R**

Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)

Engine No: 10797671N52B25AF

Reg. Date: 28/02/2011 (Man. Year: 2010)

Chassis No: WBAFP320X0C863825

Colour: Grey

Odometer: 155261 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 10/03/2021 Inspected At:

Elite Automotive Pte Ltd (HQ)
280 Woodlands Industrial Park E5, #01-17,
Harvest@Woodlands
Singapore 757322

Estimated Period of Repair: 11.0 days

Adjuster: OI SUN PIN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Scratched	0.00 F	*- F
3	1		*FRT BUMPER	Crumpled	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Crumpled	0.00 F	*- F
7	1		*FRT BUMPER GRILLE UPPER	Crumpled	0.00 F	*- F
8	1		*FRT GRILLE INNER AIR GUIDE	Crumpled	0.00 F	*- F
9	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
10	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Crumpled	0.00 F	*- F
11	1		*FRT RH HEADLAMP ASSY	Crumpled	0.00 F	*- F
12	1		*BONNET	Crumpled	0.00 F	*- F
13	2		*BONNET LOCK	Jammed	0.00 F	*- F
14	1		*BONNET INSULATOR	Necessary	0.00 F	*- F
15	1		*BONNET RUBBER	Necessary	0.00 F	*- F
16	1		*AIR CON CONDENSER	Crumpled	0.00 F	*- F
17	1		*RADIATOR	Crumpled	0.00 F	*- F
18	1		*RADIATOR COWLING	Cracked	0.00 F	*- F
19	1		*RADIATOR FAN ASSY	Deformed	0.00 F	*- F
20	1		*AIR DUCT	Crumpled	0.00 F	*- F
21	1		*FRT RH FENDER	Crumpled	0.00 F	*- F
22	1		*RH FRONT HEADLAMP BRACKET	Crumpled	0.00 F	*- F
23	1		*RH FRONT HEADLAMP STAY	Bent	0.00 F	*- F
24	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
25	1		*REAR NUMBER PLATE BASE	Scratched	0.00 F	*- F
26	1		*REAR BUMPER	Crumpled	0.00 F	*- F
27	1		*REAR BUMPER UPPER INNER	Crumpled	0.00 F	*- F
28	1		*REAR BUMPER LOWER INNER	Crumpled	0.00 F	*- F
29	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
30	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
31	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
32	1		*REAR BUMPER UNDERCOVER	Crumpled	0.00 F	*- F
33	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
34	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
35	1		*REAR END PANEL	Dented	0.00 F	*- F
36	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
37	1		*BOOTLID	Dented	0.00 F	*- F
38	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
39	1		*BOOTLID HANDLE	Cracked	0.00 F	*- F
40	2		*BOOTLID REFLECTOR	Cracked	0.00 F	*- F
41	1		*BOOTLID LOCK	Jammed	0.00 F	*- F
42	1		*BOOTLID RUBBER	Crumpled	0.00 F	*- F
43	1		*REAR EXHAUST CHROME PIPE	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) 0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >