

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003191/APA3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070017413
Claimant Vehicle No :	SKB5628R	Insured Vehicle No :	GBJ3093K
Date of Loss:	05/03/2021	Nature of Claim:	TP
		Claim No:	7212296394SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB5628R		
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)	Engine No:	27191031344999
Reg. Date:	10/06/2011 (Man. Year: 2011)	Chassis No:	WDD2040452A545863
Colour:	Blue	Odometer:	237563 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,706.94	6,745.32	6,961.62	50.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,490.00	1,450.00	3,040.00	67.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,196.94	8,195.32	10,001.62	54.96
Approved Total (Overridden) (S\$)		6,500.00		

Nett Amount (\$)	18,196.94	6,500.00	11,696.94	64.28
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (\$)		642.00		
+ Doc/Search Fee (\$)		7.45		
Nett Liability (\$)		7,149.45		

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ace Automotive Pte Ltd (HQ)
 13 Kaki Bukit Road 4, #03-22 Bartley Biz Centre
 Singapore 417807

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,391.00 FL	*1,391.00 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Necessary	135.00 FL	*135.00 FL
3	1		*FRONT BUMPER LOWER BRACKET RH	Not Necessary	110.00 FL	*- FL
4	1		*FRONT BUMPER LOWER LAMP RH	Not Necessary	325.00 FL	*- FL
5	1		*FRONT BUMPER LOWER LAMP GARNISH RH	Not Necessary	195.00 FL	*- FL
6	1		*FRONT BUMPER LOWER LAMP CHROME RH	Not Necessary	210.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	855.00 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	225.00 FL	*- FL
9	1		*FRONT BONNET	Dented	1,999.27 FL	*1,999.27 FL
10	2		*FRONT BONNET HINGE LH & RH	Not Necessary	371.20 FL	*- FL
11	1		*FRONT HEADLAMP RH	Cracked	1,872.60 FL	*1,872.60 FL
12	1		*FRONT HEADLAMP CONTROL UNIT RH	Not Necessary	571.50 FL	*- FL
13	1		*FRONT HEADLAMP PANEL	Bent	740.10 FL	*232.00 FL
14	1		*FRONT FENDER RH	Dented	925.60 FL	*925.60 FL
15	1		*FRONT FENDER INNER SILED RH	Deformed	125.00 FL	*125.00 FL
16	1		*FRONT FENDER EMBLEM	Necessary	81.00 FL	*81.00 FL
17	1		*FRONT ENGINE LOWER COVER	Not Necessary	211.00 FL	*- FL
18	1		*FRONT SHOCK ABSORBER RH	Not Necessary	355.00 FL	*- FL
19	1		*FRONT KNUCKLE ARM RH	Not Necessary	342.00 FL	*- FL
20	2		*FRONT WHEEL HUB LH & RH	Not Necessary	590.00 FL	*- FL
21	2		*FRONT WHEEL HUB BEARING LH & RH	Not Necessary	442.00 FL	*- FL
22	1		*FRONT LOWER ARM RH	Not Necessary	135.00 FL	*- FL
23	1		*FRONT TIE ROD ARM RH	Not Necessary	250.00 FL	*- FL
24	1		*FRONT BAR LINKAGE LH	Not Necessary	246.00 FL	*- FL
25	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	70.00 FS	*30.00 FS
26	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
27	1		*FRONT RIM RH	Cut	1,674.00 FS	*600.00 FS
28	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*SET FRONT FENDER CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,977.27	7,421.47
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,270.33	676.15
Total Parts (\$\$)	13,706.94	6,745.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	700.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	600.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	40.00
5	TO REMOVE AND REPLACE FRONT HEADLAMP BEAM	New	80.00	0.00
6	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO MERCEDE SPECIFICATION	New	250.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT TEST	New	180.00	80.00
8	TO REMOVE AND REPLACE UNDERCARRIAGE PART	New	250.00	0.00
Gross Labour Cost (S\$)			4,490.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >